



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 394R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DENTED	1,290.40	1,230.50
1	REAR BUMPER SKIRT	MTG CRACKED	845.40	825.20
1	TAILGATE OUTER GARNISH	SERVICEABLE	885.20	-
	LESS 20% DISCOUNT		-	-411.14
			3,021.00	1,644.56
<b><u>SPECIAL NETT ITEMS</u></b>				
1	CAR PLATE GARNISH (SN) }	DENTED	70.50	45.00
1	CAR PLATE HOLDER (SN) }	DENTED	59.20	-
			129.70	45.00
<b><u>LABOUR</u></b>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, PANEL BEAT & RESHAPE THE AFFECTED AREA.		600.00	200.00
	RESPRAY PAINT, PUTTY ON PARTS REPLACED & REPAIRED AREA.		600.00	220.00
	TO REMOVE & REFIX WIRING & CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREA FOR PROPER FUNCTIONS.		80.00	15.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			1,430.00	435.00
<b>GRAND TOTAL</b>			<b>4,580.70</b>	<b>2,124.56</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,124.56</b>

Report Ref No. CS/SMO23001891/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.