3/20/23, 10:16 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS23001893/KWY3Q2

20/03/2023 Date:

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

**Claimant Vehicle** SLV2243U Insured Vehicle No: YN7467X No:

Date of Loss: 09/02/2023 Nature of Claim: ΤP Claim No: 2023 32005356/KC

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLV2243U** 

2ZR8250581 Make & Model: TOYOTA C-HR, 1.8 (A) Engine No: Reg. Date: 26/12/2017 (Man. Year: 2017) Chassis No: ZYX102087406 667879 km Odometer: Colour: Metallic Grey

**Engine Capacity:** 1797 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Arivo 3 mm Rear Left Side: ARROW SPORT 7 mm Front Right Side: Rear Right Side: ARROW SPORT 7 mm Arivo 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,279.30	1,336.85	942.45	41.35
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,240.00	815.00	425.00	34.27
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,519.30	2,151.85	1,367.45	38.86
	Approved Total (Overridden) (S\$)		1,750.00		
	(S\$)	3,519.30	1,750.00	1,769.30	50.27
	+ GST 8.00/8.00% (S\$)	281.54	140.00	141.54	50.27
	Nett Amount (S\$)	3,800.84	1,890.00	1,910.84	50.27
	Global Sum	Settlement (S\$)	0.00		

**INSPECTION** 

Date of Assignment: 20/02/2023

Lian Her Motors (Ang Mo Kio) Date Inspected: 24/02/2023 Inspected At:

Blk 5038, Ang Mo Kio Industrial Park 2, #01-405

Singapore 569541

Estimated Period of Repair: 4.0 days

KENNETH KONG Adjuster: Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2023)

Parts: M1-SUV TOYOTA C-HR 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLV2243U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER	Buckled	775.60 FL	*545.10 FL
1		*REAR BUMPER REINFORCEMENT	Bent	455.10 FL	*455.10 FL
1		*REAR LOWER BUMPER	Dented / Cut	475.60 FL	*475.60 FL
2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
2		*REAR BUMPER REFLECTOR GARNISH	Serviceable	150.20 FL	*- FL
1		*REAR END PANEL	Repair	725.70 FL	*- FL
15		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
1		*REAR REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
			Sub Total (S\$)	2,962.40	1,705.80
		- List Item Discount on L Iten	ns 25.00/25.00% (S\$)	683.10	368.95
			Total Parts (S\$)	2,279.30	1,336.85
	1 1 1 2 2 1 15	2 2 1 15	1 *REAR BUMPER 1 *REAR BUMPER REINFORCEMENT 1 *REAR LOWER BUMPER 2 *REAR BUMPER SIDE RETAINER 2 *REAR BUMPER REFLECTOR GARNISH 1 *REAR END PANEL 15 *REAR BUMPER CLIP 1 *REAR REVERSE SENSOR nchise part. S=SpcNett. L=ListItemDisc.	1 *REAR BUMPER REINFORCEMENT Bent 1 *REAR BUMPER REINFORCEMENT Bent 1 *REAR LOWER BUMPER Dented / Cut 2 *REAR BUMPER SIDE RETAINER Serviceable 2 *REAR BUMPER REFLECTOR GARNISH Serviceable 1 *REAR END PANEL Repair 15 *REAR BUMPER CLIP Necessary 1 *REAR REVERSE SENSOR Scratched nchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$)  - List Item Discount on L Items 25.00/25.00% (S\$)	1       *REAR BUMPER       Buckled       775.60 FL         1       *REAR BUMPER REINFORCEMENT       Bent       455.10 FL         1       *REAR LOWER BUMPER       Dented / Cut       475.60 FL         2       *REAR BUMPER SIDE RETAINER       Serviceable       150.20 FL         2       *REAR BUMPER REFLECTOR GARNISH       Serviceable       150.20 FL         1       *REAR END PANEL       Repair       725.70 FL         15       *REAR BUMPER CLIP       Necessary       30.00 FS         1       *REAR REVERSE SENSOR       Scratched       200.00 FS         nchise part. S=SpcNett. L=ListItemDisc.       Sub Total (S\$)       2,962.40         - List Item Discount on L Items 25.00/25.00% (S\$)       683.10

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	600.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	600.00	400.00
3	CHECK AND RECONNECT WIRING	New	40.00	15.00
	Gross Labour Cost (S\$)		1,240.00	815.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >