

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/EG123001894/SCY3M4**Date:** 19/07/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** FBL2584G **Insured Vehicle No :** GBD9394J

Date of Loss: 14/02/2023 Nature of Claim: TP Claim No: CDMCG23000388

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBL2584G**

Make & Model: SUZUKI RV200L6, 200cc VANVAN 200 Engine No: H403113297

Reg. Date: 12/08/2016 (Man. Year: 2016) Chassis No: JS1BT2212G0100654

Colour: Blue Odometer: 177958 km

Engine Capacity: 200 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 130/80-18 Rear Tyre Size: 180/80-14

Front Left Side: Shinko 6 mm Rear Left Side: Shinko 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment: 20/02/2023

Date Inspected: 21/02/2023 Inspected At: Staxx Pte Ltd (HQ)  
1 Kaki Bukit Rd 1 #03-31 Enterprise One  
Singapore 415934

Estimated Period of Repair: 3.0 days

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqubal**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00  
-\$3,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jul 2023)	
Parts:	N/A	SUZUKI RV200L6 200cc VANVAN 200 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL2584G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >