

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23001902/TVY3E2**Date:** 05/04/2023REFERENCE

Insured/Claimant:	JEAN-DOMINIQUE IERACI	Policy No:	SP2003181425-01	
Date of Loss:	18/02/2023	Nature of Claim:	OD	Claim No: 202332005505

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	S1808CD		
Make & Model:	VOLKSWAGEN PASSAT, 1.4 TSI DSG 3623A7 (A)	Engine No:	CZP256279
Reg. Date:	25/11/2021 (Man. Year: 2020)	Chassis No:	WVWZZZ3CZME033567
Colour:	Black	Odometer:	5281 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,893.63	15,855.43	4,038.20	20.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,400.00	8,070.00	3,330.00	29.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,293.63	23,925.43	7,368.20	23.55
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	30,693.63	23,325.43	7,368.20	24.01
+ GST 8.00/8.00% (S\$)	2,455.49	1,866.03	589.46	24.01
Nett Amount (S\$)	33,149.12	25,191.46	7,957.66	24.01

INSPECTION

Date of Assignment:	21/02/2023	
Date Inspected:	21/02/2023	Inspected At: Volkswagen Group Singapore Pte Ltd (tuas) (HQ) 17 Tuas Ave 9 Singapore 639197
Estimated Period of Repair:	13.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2023)
Parts:	143	VOLKSWAGEN PASSAT 1.4 TSI DSG 3623A7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for S1808CD)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Bent	1,308.25 FS	*1,308.25 FS
2	1		*COVER FOR BUMPER PRIMED	Deformed	1,360.00 FS	*1,360.00 FS
3	1		*SPOILER SATIN BLACK	Deformed	261.88 FS	*261.88 FS
4	1		*LICENSE PLATE BRACKET SAT	Deformed	87.14 FS	*87.14 FS
5	1		*RIVET (4PCS)	Necessary	1.38 FS	*1.38 FS
6	1		*IMPACT BEAM REINFORCEMENT	Bent	741.78 FS	*741.78 FS
7	1		*FOAM INSERT	Deformed	102.33 FS	*102.33 FS
8	1		*CROSS MEMBER	Bent	178.33 FS	*178.33 FS
9	4		*POP-RIVET	Necessary	4.44 FS	*4.44 FS
10	1		*GUIDE PIECE BUMPER INNER BRACKET LH	Deformed	48.62 FS	*48.62 FS
11	1		*GUIDE PIECE BUMPER INNER BRACKET RH	Not Necessary	48.62 FS	*- FS
12	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Deformed	48.62 FS	*48.62 FS
13	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	48.62 FS	*- FS
14	1		*GUIDE PIECE BUMPER CTR BRACKET	Deformed	97.36 FS	*97.36 FS
15	1		*SET SENSOR BRACKETS	Necessary	38.40 FS	*38.40 FS
16	4		*SENSOR PRIMED	Not Necessary	560.53 FS	*- FS
17	1		*SEAL RING SATIN BLACK (4PCS)	Necessary	4.41 FS	*4.41 FS
18	1		*RADIATOR GRILLE SATIN BLA	Cut	495.16 FS	*495.16 FS
19	1		*VW SIGN BLACK / BRIGHT CHRO	Cracked	102.35 FS	*102.35 FS
20	1		*COOLING AIR GRILL SATIN B BUMPER CTR LOWER GRILLE	Deformed	147.72 FS	*147.72 FS
21	1		*DECORATIVE MOULDING BRIGH BUMPER CTR LOWER GRILLE CHROM	Cut	156.30 FS	*156.30 FS
22	1		*COOLING AIR GRILL SATIN B RHS FOG LAMP GRILLE	Cut	97.49 FS	*97.49 FS
23	1		*COVER STRIP SATIN BLACK RHS FOG LAMP GRILLE LOWER TRIM	Not Necessary	74.67 FS	*- FS
24	1		*COOLING AIR GRILL SATIN B LHS FOG LAMP GRILLE	Deformed	98.44 FS	*98.44 FS
25	1		*COVER STRIP SATIN BLACK LHS FOG LAMP GRILLE LOWER TRIM	Deformed	74.67 FS	*74.67 FS
26	1		*LED HEADLIGHT LHS H/LAMP	Cut	1,944.09 FS	*1,944.09 FS
27	1		*LED HEADLIGHT RHS H/LAMP	Cut	1,944.09 FS	*1,944.09 FS
28	1		*HALOGEN FOG LIGHTS WITH S LHS FOG LAMP	Missing	289.31 FS	*289.31 FS
29	1		*HALOGEN FOG LIGHTS WITH S RHS FOG LAMP	Not Necessary	289.31 FS	*- FS
30	1		*TEMP. SENS.	Distorted	33.21 FS	*33.21 FS
31	1		*HOLDER FOR TEMPERATURE SE	Deformed	2.81 FS	*2.81 FS
32	1		*LOCK CARRIER WITH MOUNTIN	Not Necessary	1,127.86 FS	*- FS
33	1		*SUPPORT FOR LOCK CARRIER	Not Necessary	29.40 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*AIR DUCT AIR GUIDE RH	Not Necessary	22.27 FS	*- FS
35	1		*AIR DUCT AIR GUIDE LH	Not Necessary	22.27 FS	*- FS
36	1		*R1234YF COOLANT A/C GAS (100PCS)	Not Necessary	44.64 FS	*- FS
37	1		*OIL FOR REFRIGERANT COMPR A/C OIL (0.1PCS)	Not Necessary	28.42 FS	*- FS
38	1		*SEAL RING	Not Necessary	5.58 FS	*- FS
39	1		*SEAL RING	Not Necessary	5.93 FS	*- FS
40	2		*COOLANT 1B	Not Necessary	36.20 FS	*- FS
41	1		*WASH WATER RESERVOIR WIPER TANK	Deformed	96.35 FS	*96.35 FS
42	1		*GASKET	Necessary	1.70 FS	*1.70 FS
43	1		*WATER LEVEL SWITCH	Necessary	23.93 FS	*23.93 FS
44	1		*SEAL RING	Necessary	10.98 FS	*10.98 FS
45	1		*WINDSHIELD CLEANER CONCEN	Necessary	16.00 FS	*16.00 FS
46	1		*WHEELHOUSE LINER LHS FENDER LINER LOWER	Torn	129.46 FS	*129.46 FS
47	1		*WHEELHOUSE LINER RHS FENDER LINER LOWER	Not Necessary	129.46 FS	*- FS
48	1		*SOUND BAFFLE ENGINE LOWER COVER	Torn	171.31 FS	*171.31 FS
49	1		*UNDERBODY LINING LHS	Torn	116.63 FS	*116.63 FS
50	1		*UNDERBODY LINING RHS	Torn	105.96 FS	*105.96 FS
51	1		*REAR TRANSVERSE TRIM LHS LOWER ARM COVER	Cracked	9.53 FS	*9.53 FS
52	1		*RIVET (2PCS)	Necessary	0.63 FS	*0.63 FS
53	1		*WATER DEFLECTOR STRIP BLA LHS FRT W/SCREEN SIDE MLDG	Cut	38.01 FS	*38.01 FS
54	1		*WATER DEFLECTOR STRIP BLA RHS FRT W/SCREEN SIDE MLDG	Cut	38.01 FS	*38.01 FS
55	1		*REAR VIEW MIRROR HOUSING LH	Cut	460.84 FS	*460.84 FS
56	1		*MIRROR GLASS	Not Necessary	143.40 FS	*- FS
57	1		*MIRROR CAP PRIMED	Repair	128.08 FS	*- FS
58	1		*COVER STRIP ALUMINIUM-GLO LHS FRT DOOR TOP MLDG CHROM	Not Necessary	144.52 FS	*- FS
59	1		*TRIM FOR PILLAR B BLACK LHS FRT DOOR TRIM (BLACK)	Cut	111.44 FS	*111.44 FS
60	1		*TRIM FOR DOOR WINDOW FRAM LHS REAR DOOR TRIM (BLACK)	Cut	82.72 FS	*82.72 FS
61	1		*COVER FOR DOOR PRIMED LHS FRT DOOR LOWER MLDG	Not Necessary	64.72 FS	*- FS
62	1		*DECORATIVE MOULDIG PRIME LHS FRT DOOR LOWER MLDG TRIM	Not Necessary	98.97 FS	*- FS
63	1		*CLIP (7PCS)	Necessary	2.82 FS	*2.82 FS
64	1		*REAR VIEW MIRROR HOUSING RH	Cut	460.84 FS	*460.84 FS
65	1		*MIRROR CAP PRIMED	Repair	128.08 FS	*- FS
66	1		*MIRROR GLASS	Not Necessary	568.65 FS	*- FS
67	1		*TRIM FOR PILLAR B BLACK RHS FRT DOOR TRIM	Cut	111.44 FS	*111.44 FS
68	1		*TRIM FOR DOOR WINDOW FRAM RHS REAR DOOR TRIM	Cut	82.72 FS	*82.72 FS
69	1		*COVER FOR DOOR PRIMED RHS FRT DOOR LOWER MLDG	Cut	64.72 FS	*64.72 FS
70	1		*DECORATIVE MOULDING PRIME RHS REAR DOOR LOWER MLDG TRIM	Cut	98.97 FS	*98.97 FS
71	1		*CLIP (7PCS)	Necessary	2.82 FS	*2.82 FS
72	1		*CLIP SIDE SKIRT CLIP (24PCS)	Necessary	9.68 FS	*9.68 FS
73	1		*ALLOY WHEEL ALUMINIUM SHI LHS FRT RIM	Cut	1,297.97 FS	*1,297.97 FS
74	1		*RUBBER VALVE	Necessary	2.87 FS	*2.87 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
75	1		*ALLOY WHEEL ALUMINIUM SHI RHS FRT RIM	Cut	1,297.97 FS	*1,297.97 FS
76	1		*RUBBER VALVE	Necessary	2.87 FS	*2.87 FS
77	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
78	1		*TYRE CONT 215/55/17 CPC5 SEAL (80%)	Cut	1,440.00 FS	*1,152.00 FS
79	1		*HORN	Cracked	96.26 FS	*96.26 FS
80	1		*REINFORCEMENT LOWER COVER LH	Deformed	9.40 FS	*9.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	19,893.63	15,855.43
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	B&P LEAKED CHECK, VACUUM & REGAS R1234YF	New	560.00	0.00
4	TO ALIGN LED HEADLIGHT	New	100.00	100.00
5	B&P WHEEL ALIGNMENT	New	300.00	300.00
6	R&R RIM & BALANCE	New	100.00	100.00
7	LABOUR	New	4,480.00	2,240.00
8	SPRAY PAINT	New	5,300.00	4,770.00
Gross Labour Cost (S\$)			11,400.00	8,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >