

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23001903/AYA3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100509466
Claimant Vehicle No :	SNA266D	Insured Vehicle No :	SLN8291H
Date of Loss:	17/12/2022	Nature of Claim:	TP
		Claim No:	1012092968SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA266D	Engine No:	8ARW349629
Make & Model:	TOYOTA LEXUS, 2.0 RX200T AT S/R (A)	Chassis No:	JTJBAMCA402011232
Reg. Date:	25/11/2016 (Man. Year: 2016)	Odometer:	91601 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R20	Rear Tyre Size:	235/55 R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,143.08	1,628.88	514.20	23.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	700.00	1,080.00	60.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,923.08	2,328.88	1,594.20	40.64
Approved Total (Overridden) (S\$)		1,850.00		
Nett Amount (S\$)	3,923.08	1,850.00	2,073.08	52.84
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		2,376.75		

INSPECTION

Date of Assignment:	08/02/2023		
Date Inspected:	08/02/2023	Inspected At:	Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59 Singapore 408717
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,185.60 FL	*995.00 FL
2	1		*REAR REVERSE SENSOR	Not Necessary	265.47 FL	*- FL
3	1		*REAR BUMPER GARNISH	Cut	476.26 FL	*361.00 FL
4	1		*REAR BUMPER CHROME	Cut	453.87 FL	*453.87 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,381.20	1,809.87
- List Item Discount on L Items 10.00/10.00% (S\$)	238.12	180.99
Total Parts (S\$)	2,143.08	1,628.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK INNER BRACKETS AND PANEL TO REPLACE AND ALIGN ABOVE ITEMS TO ASYMMETRICAL SPEC	New	680.00	250.00
2	TO SPRAY PAINT REAR BUMPER AND LOWER SPOILER	New	650.00	400.00
3	TO CARRY OUT REVERSE SENSOR COMPUTERIZED ADAPTATION AND SETTING	New	250.00	50.00
4	TO SUPPLY FITTINGS AND TRANSFER /INSTALL LOWER SPOILER ON BUMPER	New	200.00	0.00
			Gross Labour Cost (S\$)	1,780.00
				700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >