

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23001904/KQP3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ002403	
Claimant Vehicle No :	SHD9755E	Insured Vehicle No :	SFP711B	
Date of Loss:	09/02/2023	Nature of Claim:	TP	Claim No: M2301035

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9755E	Engine No:	2ZR2H10860
Make & Model:	TOYOTA PRIUS C, 1.5 (A)	Chassis No:	JTDKB3FU003092482
Reg. Date:	30/10/2020 (Man. Year: 2020)	Odometer:	199080 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 6 mm	Rear Left Side:	Wanli 8 mm
Front Right Side:	Wanli 6 mm	Rear Right Side:	Wanli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,668.02	1,414.03	7,253.99	83.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,010.00	4,090.00	80.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,768.02	2,424.03	11,343.99	82.39
+ GST 8.00/8.00% (S\$)	1,101.44	193.92	907.52	82.39
Nett Amount (S\$)	14,869.46	2,617.95	12,251.51	82.39

INSPECTION

Date of Assignment:	22/02/2023	
Date Inspected:	20/02/2023	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount:\$2,424.04

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	144	TOYOTA PRIUS C 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9755E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Repair	1,641.36 FL	*- FL
2	1		*FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE ,LH	Serviceable	243.81 FL	*- FL
3	1		*HANDLE ASSY ,FRONT DOOR OUTSIDE ,LH	Serviceable	493.40 FL	*- FL
4	1		*WEATHERSTRIP ,FRONT DOOR ,LH	Serviceable	292.32 FL	*- FL
5	1		*HINGE ASSY ,FRONT DOOR, LOWER LH	Repair	139.86 FL	*- FL
6	1		*HINGE ASSY ,FRONT DOOR, UPPER LH	Repair	123.06 FL	*- FL
7	1		*TAPE ,BLACK OUT ,NO.1 FRT LH	Not Necessary	16.91 FL	*- FL
8	1		*TAPE ,BLACK OUT ,NO.2 FRT LH	Not Necessary	55.02 FL	*- FL
9	1		*TAPE ,BLACK OUT ,NO.3 FRT LH	Not Necessary	33.29 FL	*- FL
10	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH	Serviceable	1,161.83 FL	*- FL
11	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH	Serviceable	300.62 FL	*- FL
12	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Bent	1,634.33 FL	*1,634.33 FL
13	1		*FRAME SUB-ASSY ,REAR DOOR OUTSIDE HANDLE ,LH	Serviceable	243.81 FL	*- FL
14	1		*HANDLE ASSY ,REAR DOOR OUTSIDE ,LH	Serviceable	123.06 FL	*- FL
15	1		*WEATHERSTRIP,REAR DOOR OPENING TRIM ,LH	Serviceable	369.60 FL	*- FL
16	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Repair	109.62 FL	*- FL
17	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Repair	124.74 FL	*- FL
18	1		*TAPE ,BLACK OUT,NO.1 REAR LH	Necessary	27.62 FL	*27.62 FL
19	1		*TAPE ,BLACK OUT,NO.2 REAR LH	Necessary	44.00 FL	*44.00 FL
20	1		*TAPE ,BLACK OUT,NO.3 REAR LH	Necessary	19.43 FL	*19.43 FL
21	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,LH	Serviceable	1,161.83 FL	*- FL
22	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	Serviceable	260.51 FL	*- FL
23	1		*PANEL SUB-ASSY ,QUARTER ,LH	Repair	1,099.46 FL	*- FL
24	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Repair	624.54 FL	*- FL
25	2		*SET DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
26	2		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	*- FS
27	1		*DOOR STICKER TRANSCAB	Necessary	350.00 FS	*60.00 FS
28	1		*DOOR STICKER TEL NO	Necessary	100.00 FS	*60.00 FS
29	1		*SET CLIP ,ROCKER PANEL MOULDING	Not Necessary	65.00 FS	*- FS
30	1		*SET FENDER CLIP	Not Necessary	130.00 FS	*- FS
31	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,254.03	1,845.38
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,586.01	431.35
Total Parts (\$\$)	8,668.02	1,414.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	300.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	660.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,100.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >