

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23001907/KQY3Q2**Date:** 11/04/2023**REFERENCE**

Insured/Claimant: AUTOBAHN RENT A CAR PTE LTD Policy No: SPMF1000000542

Date of Loss: 04/02/2023

Nature of Claim: OD

Claim No: ABRAISCL2023-00018JK

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLD1615G**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4031097

Reg. Date: 06/06/2016 (Man. Year: 2015)

Chassis No: RU11111095

Colour: Metallic Light Grey

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: S\$47,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: ZEXTOUR 6 mm

Rear Left Side: Firenza 3 mm

Front Right Side: ZEXTOUR 6 mm

Rear Right Side: Firenza 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,687.00	15,053.50	1,633.50	9.79
Miscellaneous Items	200.00	60.00	140.00	70.00
Labour	3,560.00	2,330.00	1,230.00	34.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,447.00	17,443.50	3,003.50	14.69
Approved Total (Overridden) (S\$)		13,800.00		
- Excess (S\$)	0.00	4,500.00	-4,500.00	
(S\$)	20,447.00	9,300.00	11,147.00	54.52
+ GST 8.00/8.00% (S\$)	1,635.76	744.00	891.76	54.52
Nett Amount (S\$)	22,082.76	10,044.00	12,038.76	54.52

INSPECTION

Date of Assignment: 20/02/2023 Present Location:

Ding Auto Pte Ltd (HQ)

Date Inspected: 21/02/2023 Inspected At:

BLK 10 #01-20 SIN MING IND EST SEC C

SINGAPORE 575645

Repairer: Ding Auto Pte Ltd (HQ)

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1615G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Bent	240.00 F	*240.00 F
2	1		*FRT BUMPER RETAINER RH (WCP)	Distorted	25.00 F	*25.00 F
3	1		*FRT BUMPER RETAINER LH (WCP)	Distorted	25.00 F	*25.00 F
4	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	230.00 F	*230.00 F
5	1		*FRT BUMPER LOWER GARNISH (WCP)	Distorted	180.00 F	*180.00 F
6	1		*BONNET (WCP)	Bent	490.00 F	*490.00 F
7	1		*BONNET HINGE RH (WCP)	Distorted	45.00 F	*45.00 F
8	1		*BONNET HINGE LH (WCP)	Distorted	45.00 F	*45.00 F
9	1		*BONNET INSULATOR (WCP)	Cracked	105.00 F	*105.00 F
10	1		*BONNET LOCK (WCP)	Bent	95.00 F	*95.00 F
11	1		*BONNET STAND (WCP)	Serviceable	45.00 F	*- F
12	1		*FRT GRILLE BASE (WCP)	Cracked	260.00 F	*260.00 F
13	1		*FRT GRILLE CHROME MLDG (WCP)	Dented	240.00 F	*240.00 F
14	1		*FRT LOWER GRILLE (WCP)	Cracked	85.00 F	*85.00 F
15	1		*FRT GRILLE CTR BRACKET (WCP)	Bent	40.00 F	*40.00 F
16	1		*GRILLE BADGE (WCP)	Necessary	25.00 F	*25.00 F
17	1		*FRT SUPPORT PANEL CPL (WCP)	Bent	420.00 F	*420.00 F
18	1		*FRT SUPPORT PANEL UPPER GARNISH (WCP)	Cracked	65.00 F	*65.00 F
19	1		*FRT FENDER RH (WCP)	Bent	245.00 F	*245.00 F
20	1		*FRT FENDER LH (WCP)	Buckled	245.00 F	*245.00 F
21	1		*FRT FENDER INNER COVER RH (WCP)	Serviceable	110.00 F	*- F
22	1		*FRT FENDER INNER COVER LH (WCP)	Serviceable	110.00 F	*- F
23	1		*FRT FENDER ARCH MLDG RH (WCP)	Distorted	75.00 F	*75.00 F
24	1		*FRT FENDER ARCH MLDG LH (WCP)	Distorted	75.00 F	*75.00 F
25	1		*LOWER SIDE SKIRTING LH (WCP)	Serviceable	190.00 F	*- F
26	1		*WIPER COWL PANEL (WCP)	Repair	210.00 F	*- F
27	1		*WIPER COWL PANEL END GARNISH RH (WCP)	Serviceable	40.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*WIPER COWL PANEL END GARNISH LH (WCP)	Serviceable	40.00 F	*- F
29	1		*HEADLAMP ASSY RH (WCP)	Mtg Broken	1,150.00 F	*1,150.00 F
30	1		*HEADLAMP ASSY LH (WCP)	Mtg Broken	1,150.00 F	*1,150.00 F
31	1		*HEADLAMP BRACKET RH (WCP)	Cracked	35.00 F	*35.00 F
32	1		*HEADLAMP BRACKET LH (WCP)	Cracked	35.00 F	*35.00 F
33	1		*FOG LAMP ASSY RH (WCP)	Serviceable	165.00 F	*- F
34	1		*FOG LAMP ASSY LH (WCP)	Serviceable	165.00 F	*- F
35	1		*RADIATOR ASSY (WCP)	Bent	890.00 F	*890.00 F
36	1		*RADIATOR AIR GUIDE RH (WCP)	Cracked	55.00 F	*55.00 F
37	1		*RADIATOR AIR GUIDE LH (WCP)	Cracked	55.00 F	*55.00 F
38	1		*RADIATOR UPPER BRACKET RH (WCP)	Distorted	30.00 F	*30.00 F
39	1		*RADIATOR UPPER BRACKET LH (WCP)	Distorted	30.00 F	*30.00 F
40	1		*CONDENSOR ASSY (WCP)	Punctured	460.00 F	*460.00 F
41	1		*FAN SHOURD (WCP)	Cracked	105.00 F	*105.00 F
42	1		*FAN SHOURD - RADIATOR (WCP)	Cracked	105.00 F	*105.00 F
43	1		*FAN MOTOR (WCP)	Jammed	220.00 F	*220.00 F
44	1		*FAN MOTOR - RADIATOR (WCP)	Jammed	220.00 F	*220.00 F
45	1		*FAN BLADE (WCP)	Distorted	60.00 F	*60.00 F
46	1		*FAN BLADE - RADIATOR (WCP)	Distorted	60.00 F	*60.00 F
47	1		*A/C SUCTION HOSE (WCP)	Dented	150.00 F	*150.00 F
48	1		*A/C DISCHARGE HOSE (WCP)	Bent	150.00 F	*150.00 F
49	1		*WASHER TANK (WCP)	Dented	75.00 F	*75.00 F
50	1		*AIR FILTER HOUSING (WCP)	Cracked	140.00 F	*140.00 F
51	1		*AIR FILTER DUCT (WCP)	Cracked	55.00 F	*55.00 F
52	1		*AIR FILTER HOSE (WCP)	Serviceable	50.00 F	*- F
53	1		*HORN (WCP)	Serviceable	45.00 F	*- F
54	1		*ENGINE LOWER COVER (WCP)	Serviceable	105.00 F	*- F
55	1		*ENGINE SIDE COVER LH (WCP)	Serviceable	60.00 F	*- F
56	1		*DASHBOARD ASSY (WCP)	Torn	720.00 F	*720.00 F
57	1		*DRIVER AIRBAG (WCP)	Burst	990.00 F	*990.00 F
58	1		*PASSENGER AIRBAG (WCP)	Burst	1,250.00 F	*1,250.00 F
59	1		*AIRBAG ECU (WCP)	Necessary	680.00 F	*680.00 F
60	1		*SEAT BELT ASSY RH (WCP)	Jammed	465.00 F	*465.00 F
61	1		*SEAT BELT ASSY LH (WCP)	Jammed	465.00 F	*465.00 F
62	1		*CTR PILLAR GARNISH RH (WCP)	Serviceable	75.00 F	*- F
63	1		*CTR PILLAR GARNISH LH (WCP)	Serviceable	75.00 F	*- F

Report was unsubmitted during this print-out.

4/11/23, 12:27 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
<u>Supplementary #1</u>						
64	1		*AIR INTAKE MANIFOLD (WCP)	Cracked	360.00 F	*360.00 F
65	1		*AIR INTAKE MANIFOLD HOSE (WCP)	Punctured	25.00 F	*25.00 F
66	1		*FOG LAMP COVER RH (WCP)	Dented	30.00 F	*30.00 F
67	1		*FRONT NUMBER PLATE (WCP)	Dented	25.00 F	*25.00 F
68	1		*BATTERY SWITCH COVER (WCP)	Dented	20.00 F	*20.00 F
69	1		*EXPANSION TANK (WCP)	Dented	45.00 F	*45.00 F
70	1		*BATTERY TRAY (WCP)	Cracked	20.00 F	*20.00 F
71	1		*RESONATOR CHAMBER (WCP)	Dented	105.00 F	*105.00 F
F=Franchise part.						
					Sub Total (\$\$)	15,170.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	1,517.00
					Total Parts (\$\$)	16,687.00
						13,685.00
						1,368.50
						15,053.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRT BUMPER, INNER COVER, SEAL MLDG, GRILLE PANEL & GARNISH - CLIPS	200.00	60.00
Sub Total (\$\$)			200.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,400.00	700.00
2	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL	New	1,400.00	1,000.00
3	REMOVE & REFIT - DASHBOARD COMPONENTS	New	250.00	250.00
4	REFILL - RADIATOR COOLANT	New	80.00	50.00
5	REFILL - AIR COND GAS	New	80.00	80.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
6	STRAIGHTEN AND ALIGN - FRONT CHASSIS RH & LH	New	350.00	250.00
Gross Labour Cost (\$\$)			3,560.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >