

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunios Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS23001909/RCY3Q2**Date:** 14/07/2023**REFERENCE**

Insured/Claimant: QUEK CHIN MING Policy No: MPC23P00021300  
Date of Loss: 18/02/2023 Nature of Claim: OD Claim No: DMPC2300109H/AF

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLW3103D**  
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR0A53483  
Reg. Date: 06/02/2018 (Man. Year: 2017) Chassis No: JTDGG20W30J008775  
Colour: Grey Odometer: 73632 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: S\$83,000.00  
Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,377.00	2,574.00	803.00	23.78
Miscellaneous Items	145.00	115.00	30.00	20.69
Labour	2,560.00	1,910.00	650.00	25.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,082.00</b>	<b>4,599.00</b>	<b>1,483.00</b>	<b>24.38</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,650.00</b>		
<b>(\$\$)</b>	6,082.00	3,650.00	2,432.00	39.99
<b>+ GST 8.00/8.00% (\$\$)</b>	486.56	292.00	194.56	39.99
<b>Nett Amount (\$\$)</b>	<b>6,568.56</b>	<b>3,942.00</b>	<b>2,626.56</b>	<b>39.99</b>

**INSPECTION**

Date of Assignment: 21/02/2023 Present Location: Wah Hong Motors & Credit Pte Ltd (HQ)  
Date Inspected: 22/02/2023 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)  
Estimated Period of Repair: 7.0 days 38 Toh Guan Road East, #01-57, Enterprise Hub  
Singapore 608581

**Adjuster:** MOHD RASUL**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jul 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW3103D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet	Buckled	300.00 F	*300.00 F
2	1		*Bonnet hinge RH/LH@2*\$40	Bent	80.00 F	*80.00 F
3	1		*Bonnet logo badge	Necessary	30.00 F	*30.00 F
4	1		*Bonnet lock	Not Necessary	70.00 F	*- F
5	1		*Center grille with outer chrome	Bent	140.00 F	*140.00 F
6	1		*Front bumper	Cracked	240.00 F	*240.00 F
7	1		*Front bumper side retainer RH/LH@2*\$40	Not Necessary	80.00 F	*- F
8	1		*Headlamp RH/LH@2*\$400	Cracked	800.00 F	*800.00 F
9	1		*Support panel	Repair	580.00 F	*- F
10	1		*Brace panel	Bent	70.00 F	*70.00 F
11	1		*Condenser	Bent	480.00 F	*480.00 F
12	1		*Front reinforcement	Bent	140.00 F	*140.00 F
13	1		*Front bumper sponge	Cracked	60.00 F	*60.00 F
14	1		*Front fender RH/LH (Repair refer to labour) (NPA)	Repair	0.00 F	*- F
15	1		*Front door RH/LH (Repair refer to labour) (NPA)	Repair	0.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	3,070.00	2,340.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	307.00	234.00
Total Parts (\$\$)	3,377.00	2,574.00

Report was unsubmitted during this print-out.
-----------------------------------------------

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>Center grille clips</b> (Necessary)	25.00	20.00
2	1	<b>Coolant</b> (Necessary)	50.00	30.00
3	1	<b>Front bumper clips</b> (Necessary)	35.00	30.00
4	1	<b>Front car plate with holder</b> (Bent)	35.00	35.00
<b>Sub Total (\$\$)</b>			<b>145.00</b>	<b>115.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,000.00	600.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,400.00	1,200.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00	30.00
4	To remove and refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	New	100.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,560.00</b>	<b>1,910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >