

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001911/UQP3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNA00015232201

Claimant Vehicle No : CB8866U **Insured Vehicle No :** PA8944D

Date of Loss: 17/02/2023 Nature of Claim: TP Claim No: SNM23D201310/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB8866U**

Make & Model: TOYOTA HIACE, 2.8 D DX DIESEL TURBO AT 2WD (A) Engine No: 1KDB104364

Reg. Date: 22/04/2022 (Man. Year: 2021) Chassis No: JTFST22P000040527

Colour: Silver Odometer: 14113 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,687.30	3,120.10	2,567.20	45.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,430.00	630.00	30.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,747.30	4,550.10	3,197.20	41.27
+ GST 8.00/8.00% (S\$)	619.78	364.01	255.77	41.27
Nett Amount (S\$)	8,367.08	4,914.11	3,452.97	41.27

INSPECTION

Date of Assignment: 20/02/2023

Date Inspected: 23/02/2023 Inspected At: Stytech Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	213	TOYOTA HIACE 2.8 D DX DIESEL TURBO AT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB8866U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	2,369.60 F	*2,369.60 FL
2	2		*REAR BOOT UPPER BRINKING LIGHT	Necessary	150.00 FS	*100.00 FS
3	1		*REAR BOOT GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
4	1		*REAR BOOT EMBLEM	Not Necessary	68.00 F	*- FL
5	1		*REAR BOOT TOYOTA STICKER	Necessary	52.00 F	*52.00 FL
6	1		*REAR BOOT HIACE STICKER	Necessary	56.00 F	*56.00 FL
7	1		*REAR BOOT 60KM/H STICKER	Necessary	15.00 FS	*10.00 FS
8	1		*REAR BOOT EMERGENCY DOOR STICKER	Necessary	15.00 FS	*15.00 FS
9	1		*REAR BOOT PULL TO OPEN STICKER	Necessary	15.00 FS	*15.00 FS
10	1		*REAR BOOT HANDICAP STICKER	Necessary	35.00 FS	*35.00 FS
11	1		*REAR BOOT LOCK	Serviceable	195.80 F	*- FL
12	1		*RIGHT TAILLAMP	Scratched	487.50 F	*408.10 FL
13	1		*REAR BUMPER	Dented	781.40 F	*681.10 FL
14	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
15	2		*REAR BUMPER RETAINER (LEFT & RIGHT)	Not Necessary	172.00 F	*- FL
16	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
17	1		*REAR END PANEL	Repair	985.00 F	*- FL
					Sub Total (S\$)	5,687.30 4,011.80
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 891.70
					Total Parts (S\$)	5,687.30 3,120.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R REAR WINDSCREEN	New	150.00	120.00
2	TRANSFER TAILGATE MECHANISM	New	150.00	60.00
3	ANTI RUST PROOF	New	80.00	30.00
4	CHECK WIRING	New	80.00	20.00
5	PANEL BEATING	New	700.00	600.00
6	PAINT WORK	New	900.00	600.00
Gross Labour Cost (S\$)			2,060.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >