

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/C1123001911/49P3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: CB88664at Workshop m/s stytech 10am

of _____

Insured: PA8944D

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 130k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 027E
Vehicle: IN / OUTDate: _____ Person Contacted: 1740Veh No: CB88664 Yr Regn: 22/04/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/Make: Toyota Hiace High roof commuter 2982Colour: silver A/C: Insured / Std / NI / NASp. Reading: 14113 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFST224V000 K0527Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Ni / S/Rim / STD A/Rim orTyre Size: F: 195-1215

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 17/02/23 D.O.I. 23/02/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

CB88664 027E Rep 15k.8/3/23 11/2 4550.10 in hand Winston. Ched 3097.20, 412)

Date/Time, File Pass to?

1) 15/3 11/23

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)Report Format: NER-TPLump Sum / I.B.I. (\$) 4550.10

Vehicle: CB8866U

Make & Model: TOYOTA HIACE

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Boot			\$ 2,369.60	Red 3.00 ✓
2	Rear Boot Upper Brinking Light	2		\$ 150.00 SN	new 100 s/w
3	Rear Boot Glass Sealant			\$ 60.00 SN	new 40 s/w
4	Rear Boot "Emblem"			\$ 68.00	new X
5	Rear Boot "TOYOTA" Sticker			\$ 52.00	new ✓
6	Rear Boot "HIACE" Sticker			\$ 56.00	new ✓
7	Rear Boot "60km/h" Sticker			\$ 15.00 SN	new 10 s/w
8	Rear Boot "EMERGENCY DOOR" Sticker			\$ 15.00 SN	new ✓ s/w
9	Rear Boot "PULL TO OPEN" Sticker			\$ 15.00 SN	new ✓ s/w
10	Rear Boot "Handicap" Sticker			\$ 35.00 SN	new ✓ s/w
11	Rear Boot Lock			\$ 195.80	SPX X
9	Right Taillamp		408.10	\$ 487.50	SPX ✓
10	Rear Bumper		681.10	\$ 781.40	new ✓
11	Rear Bumper Chips			\$ 30.00 SN	new s/w ✓
12	Rear Bumper Retainer (Left & Right)	2	\$86.00	\$ 172.00	new X
13	Rear Bumper Reverse Sensor		1 set	\$ 200.00 SN	should s/w
14	Rear End Panel			\$ 985.00	R X
15			250		
Labour					
1	Glass Fixing 70 R & R rear windscreen			\$ 150.00	120
2	Transfer Boot 70:1 gate mechanism			\$ 150.00	60
3	Anti Rust Proof			\$ 80.00	30
4	Check Wiring			\$ 80.00	20

5	Panel Beating			\$ 700.00	600
6	Paint Work			\$ 900.00	600

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #01-03
 Kaki Bukit Autohub, Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

Not Adult
P/P 5 4550.10
4 Lys.
23/2/23
the p/bc like-poly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 3566-80
252
P- 2675-10
S.N- 445
L- 1430
4550.10