

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG23001912/AQY3E2**Date:** 17/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220022221
Claimant Vehicle No :	SLE6336Z	Insured Vehicle No :	SMK5825S
Date of Loss:	18/02/2023	Nature of Claim:	TP
		Claim No:	1867275310SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE6336Z		
Make & Model:	MERCEDES-BENZ A200, 1.3 (A)	Engine No:	28291480058471
Reg. Date:	08/11/2019 (Man. Year: 2019)	Chassis No:	WDD1771872W017929
Colour:	Red	Odometer:	54717 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,629.50	11,887.81	21,741.69	64.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,880.00	3,100.00	3,780.00	54.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,509.50	14,987.81	25,521.69	63.00
Approved Total (Overridden) (S\$)		12,000.00		
Nett Amount (S\$)	40,509.50	12,000.00	28,509.50	70.38

INSPECTION

Date of Assignment:	21/02/2023	JDM AUTOCARE (HQ)
Date Inspected:	21/02/2023 Inspected At:	1 KAKI BUKIT AVENUE 6 #01-51, Autobay @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	2,388.00 FL	*- FL
2	1		*FRONT DOOR RH MIRROR BRACKET WITH MOTOR	Not Necessary	1,745.00 FL	*- FL
3	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	289.00 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	342.10 FL	*- FL
5	1		*FRONT DOOR HINGE (UPPER) RH	Not Necessary	101.31 FL	*- FL
6	1		*FRONT DOOR HINGE (LOWER) RH	Not Necessary	101.31 FL	*- FL
7	1		*FRONT DOOR INNER LOCK RH	Not Necessary	469.10 FL	*- FL
8	1		*FRONT DOOR INNER TRIM RH	Not Necessary	1,264.31 FL	*- FL
9	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	796.31 FL	*- FL
10	1		*FRONT DOOR REGULATOR RH	Not Necessary	364.51 FL	*- FL
11	1		*REAR DOOR RH	Repair	1,950.00 FL	*- FL
12	1		*REAR DOOR RUBBER RH	Not Necessary	255.00 FL	*- FL
13	1		*FRONT DOOR LH	Dented	2,388.00 FL	*2,388.00 FL
14	1		*FRONT DOOR LH MIRROR BRACKET WITH MOTOR	Cut	1,745.00 FL	*1,745.00 FL
15	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	289.00 FL	*289.00 FL
16	1		*FRONT DOOR OUTER HANDLE LH	Repair	342.10 FL	*- FL
17	1		*FRONT DOOR HINGE (UPPER) LH	Not Necessary	101.31 FL	*- FL
18	1		*FRONT DOOR HINGE (LOWER) LH	Not Necessary	101.31 FL	*- FL
19	1		*FRONT DOOR INNER LOCK RH	Not Necessary	469.10 FL	*- FL
20	1		*FRONT DOOR INNER TRIM LH	Not Necessary	1,264.31 FL	*- FL
21	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	796.31 FL	*- FL
22	1		*FRONT DOOR REGULATOR LH	Not Necessary	364.51 FL	*- FL
23	1		*REAR DOOR LH	Repair	1,950.00 FL	*- FL
24	1		*REAR DOOR RUBBER LH	Not Necessary	255.00 FL	*- FL
25	1		*FRONT BUMPER	Repair	1,353.79 FL	*- FL
26	1		*LEFT HEADLAMP	Cut	2,506.71 FL	*2,506.71 FL
27	1		*RIGHT HEAD LAMP	Not Necessary	2,506.71 FL	*- FL
28	1		*FRONT BUMPER MB EMBLEM	Necessary	61.80 FL	*61.80 FL
29	1		*FRONT BASIC MOUNTING FOR BUMPER	Not Necessary	142.47 FL	*- FL
30	1		*LEFT FRONT BUMPER SUPPORT	Not Necessary	14.65 FL	*- FL
31	1		*RIGHT FRONT BUMPER SUPPORT	Not Necessary	14.65 FL	*- FL
32	1		*FRONT LOWER ARM LH	Bent	626.75 FL	*626.75 FL
33	1		*FRONT SHOCK ABSORBER LH	Not Necessary	672.00 FL	*- FL
34	1		*FRONT KNUCKLE ARM LH	Damaged	689.00 FL	*689.00 FL
35	1		*FRONT KNUCKLE ARM BEARING LH	Damaged	460.00 FL	*460.00 FL
36	1		*FRONT CONTROL ARM LH	Not Necessary	613.50 FL	*- FL
37	1		*FRONT UPPER ARM LH	Not Necessary	588.80 FL	*- FL
38	1		*FRONT LOWER ARM RH	Bent	626.75 FL	*626.75 FL
39	1		*FRONT SHOCK ABSORBER RH	Not Necessary	672.00 FL	*- FL
40	1		*FRONT KNUCKLE ARM RH	Damaged	689.00 FL	*689.00 FL
41	1		*FRONT KNUCKLE ARM BEARING RH	Damaged	460.00 FL	*460.00 FL
42	1		*FRONT CONTROL ARM RH	Not Necessary	613.50 FL	*- FL
43	1		*FRONT UPPER ARM RH	Not Necessary	588.80 FL	*- FL
44	1		*FRONT RH RIM	Cut	1,500.00 FS	*1,200.00 FS
45	1		*FRONT LH RIM	Cut	1,500.00 FS	*1,200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	37,032.78	12,942.01
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,403.28	1,054.20
Total Parts (\$\$)	33,629.50	11,887.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET	New	200.00	0.00
2	TO APPLY UNDERSEALING	New	180.00	80.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	1,800.00	1,400.00
4	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	New	2,000.00	600.00
5	TO DISCONNECT DOOR AIR BAG WIRE & REWIRE, TO RESET AIR BAG SYSTEM	New	300.00	0.00
6	QUARTZ CERAMIC COATING	New	1,200.00	500.00
7	TO TRANSFER 4 DOOR	New	500.00	80.00
8	COMPUTERISED AND CHECK FR WHEEL ALIGNMENT	New	200.00	80.00
9	REMOVE & REPLACE FR UNDERCARRIAGE PARTS	New	500.00	360.00
Gross Labour Cost (\$)			6,880.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >