

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001914/AQP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00099752202
<b>Claimant Vehicle No :</b>	SDF5225G	<b>Insured Vehicle No :</b>	GBG7148B
Date of Loss:	17/02/2023	Nature of Claim:	TP
		Claim No:	SNM23D201328/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDF5225G</b>	Engine No:	MR20562865W
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Chassis No:	SJNFBAJ11U2420818
Reg. Date:	06/05/2019 (Man. Year: 2018)	Odometer:	56002 km
Colour:	Brown		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,214.92	9,393.92	6,821.00	42.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	2,160.00	2,350.00	52.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,724.92</b>	<b>11,553.92</b>	<b>9,171.00</b>	<b>44.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,724.92</b>	<b>9,200.00</b>	<b>11,524.92</b>	<b>55.61</b>

**INSPECTION**

Date of Assignment:	20/02/2023		1 KAKI BUKIT AVENUE 6
Date Inspected:	21/02/2023	Inspected At:	#02-11 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	7.0 days		Repairer:Automobile Hub Enterprise

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDF5225G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	755.40 FL	*755.40 FL
2	2		*REAR BUMPER SIDE HOLDER	Damaged	71.80 FL	*71.80 FL
3	1		*REAR BUMPER TOW COVER	Deformed	26.80 FL	*26.80 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	619.20 FL	*619.20 FL
5	2		*REAR BUMPER REINFORCEMENT STAY	Bent	252.00 FL	*252.00 FL
6	1		*REAR BUMPER REFLECTOR	N/S Cracked	133.80 FL	*66.90 FL
7	1		*REAR BUMPER LOWER	Deformed	369.90 FL	*369.90 FL
8	2		*REAR BUMPER LOWER GARNISH	Deformed	596.40 FL	*596.40 FL
9	1		*REAR BUMPER SPONGE	Cracked	126.40 FL	*126.40 FL
10	1		*REAR END PANEL	Dented	482.60 FL	*482.60 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	163.50 FL	*163.50 FL
12	1		*REAR ANTENNA SENSOR	Damaged	165.40 FL	*165.40 FL
13	1		*TAILLAMP	N/S Cracked	647.40 FL	*323.20 FL
14	1		*TAILGATE	Dented	2,936.80 FL	*2,936.80 FL
15	1		*TAILGATE LOCK	Damaged	168.90 FL	*168.90 FL
16	2		*TAILGATE WEATHERSTRIPE	Not Necessary	184.70 FL	*- FL
17	1		*TAILGATE INNER TRIM BOARD	Cracked	316.50 FL	*316.50 FL
18	1		*TAILGATE OUTER GARNISH	Not Necessary	336.20 FL	*- FL
19	2		*TAILGATE REFLECTOR	Not Necessary	470.80 FL	*- FL
20	2		*TAILGATE DAMPER	Not Necessary	462.40 FL	*- FL
21	1		*TAILGATE GLASS MOULDING	Necessary	124.10 FL	*124.10 FL
22	1		*TAILGATE PULL POCKET	Not Necessary	26.10 FL	*- FL
23	1		*NISSAN LOGO	Not Necessary	59.70 FL	*- FL
24	1		*QASHQAI EMBLEM	Necessary	87.10 FL	*87.10 FL
25	2		*REAR FENDER ARC GARNISH	Cracked	966.20 FL	*966.20 FL
26	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	723.40 FL	*- FL
27	2		*REAR FENDER INNER SHIELD	Not Necessary	404.40 FL	*- FL
28	1		*SPARE TYRE PANEL	Repair	1,280.80 FL	*- FL
29	1		*SPARE TYRE PANEL TOP BOARD OUTER	Not Necessary	527.30 FL	*- FL
30	1		*SPARE TYRE PANEL TOP BOARD INNER	Not Necessary	467.20 FL	*- FL
31	1		*SPARE TYRE PANEL TOP UPHOLSTERY BOARD	Not Necessary	290.40 FL	*- FL
32	1		*TOOLS TRAY SPONGE	Deformed	268.40 FL	*268.40 FL
33	1		*REAR EXHAUST PIPE	Dented	830.40 FL	*830.40 FL
34	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	36.40 FL	*- FL
35	1		*REAR EXHAUST PIPE GASKET	Necessary	30.90 FL	*30.90 FL
36	1		*CENTRE EXHAUST PIPE	Repair	829.10 FL	*- FL
37	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
38	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
39	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*SET REVERSE SENSOR (4 PIECE SET)	Damaged	400.00 FS	*300.00 FS
41	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
42	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
43	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
44	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
45	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
46	2		*SET REAR FENDER ARC GARNISH CLIPS	Necessary	40.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

5/15/23, 11:50 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
48	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
49	1		*SPARE TYRE INSULATION PAD	Not Necessary	280.00 FS	*- FS
50	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					<b>Sub Total (\$\$)</b>	<b>17,838.80</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,623.88</b>
					<b>Total Parts (\$\$)</b>	<b>16,214.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,600.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	800.00
3	WIRING CHECK	New	100.00	30.00
4	TO APPLY TUFF COAT	New	180.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
8	TO REMOVE UPHOLSTERY & REAR SEAT	New	300.00	60.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE REAR & CENTRE EXHAUST PIPES	New	300.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>4,510.00</b>	<b>2,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >