

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23001915/UPA3Q2  
**Date:** 27/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900119915
<b>Claimant Vehicle No :</b>	FBA6865C	<b>Insured Vehicle No :</b>	SMN583G
Date of Loss:	14/12/2022	Nature of Claim:	TP
		Claim No:	1708061455SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>FBA6865C</b>	Engine No:	M312M24891
Make & Model:	PIAGGIO VESPA GT200A, 198cc	Chassis No:	ZAPM3120000024105
Reg. Date:	21/07/2006 (Man. Year: 2006)	Odometer:	76014 km
Colour:	Orange		
Engine Capacity:	198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	120/70-12	Rear Tyre Size:	130/70-12
Front Left Side:	Milas 6 mm	Rear Left Side:	Milas 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,035.00	225.00	810.00	78.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	320.00	150.00	170.00	53.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,355.00</b>	<b>375.00</b>	<b>980.00</b>	<b>72.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>300.00</b>		
<b>Nett Amount (S\$)</b>	<b>1,355.00</b>	<b>300.00</b>	<b>1,055.00</b>	<b>77.86</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	21/02/2023		
Date Inspected:	21/02/2023	Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	2.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*MAIN STAND	Repair	220.00 FL	*- FL	
2	1		*ENGINE COVER	Repair	680.00 FL	*- FL	
3	1		*ENGINE COVER (CHROME)	Cut	250.00 FL	*250.00 FL	
					<b>Sub Total (\$)</b>	<b>1,150.00</b>	<b>250.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	115.00	25.00
					<b>Total Parts (\$)</b>	<b>1,035.00</b>	<b>225.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING (NPA)	New	0.00	0.00
2	TO PROVIDE LABOUR	New	320.00	150.00
			<b>Gross Labour Cost (S\$)</b>	<b>320.00</b>
				<b>150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >