

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001916/UVP3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00011952202

Claimant Vehicle No : EX5959R **Insured Vehicle No :** PC6122L

Date of Loss: 17/02/2023 Nature of Claim: TP Claim No: SNM23D201292/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EX5959R**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2289516A

Reg. Date: 30/08/2016 (Man. Year: 2016) Chassis No: SJNFEAJ11U1687814

Colour: Grey Odometer: 196285 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,754.64	2,433.68	2,320.96	48.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,878.00	2,268.00	1,610.00	41.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,632.64	4,701.68	3,930.96	45.54
+ GST 8.00/8.00% (S\$)	690.61	376.13	314.48	45.54
Nett Amount (S\$)	9,323.25	5,077.81	4,245.44	45.54

INSPECTION

Date of Assignment: 21/02/2023

Date Inspected: 22/02/2023 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EX5959R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH RR FENDER WHEEL ARC MOULDING	Not Necessary	584.20 FN	*- FN
2	1		*RH RR FENDER WHEEL ARC MOULDING	Not Necessary	584.20 FN	*- FN
3	1		*ORNAMENT-BACK DOOR NISSAN	Not Necessary	101.90 FN	*- FN
4	1		*EMBLEM -REAR NISSAN	Necessary	70.00 FN	*70.00 FN
5	1		*LH REFLECTOR RR BUMPER	Not Necessary	66.90 FN	*- FN
6	1		*RH REFLECTOR RR BUMPER	Not Necessary	66.90 FN	*- FN
7	1		*LH RR COMB LAMP	Not Necessary	412.10 FN	*- FN
8	1		*RH RR COMB LAMP	Not Necessary	412.10 FN	*- FN
9	1		*WEATHER STRIP HATCHBACK DOOR	Not Necessary	198.40 FN	*- FN
10	1		*PLATE -LUGGAGE REAR GARNISH	Twisted	74.30 FN	*74.30 FN
11	1		*REAR END PANEL	Dented	573.80 FN	*573.80 FN
12	10		*CLIP RR BUMPER BRACKET	Necessary	14.00 FN	*14.00 FN
13	1		*LH SIDE BRACKET RR BUMPER	Not Necessary	42.00 FN	*- FN
14	1		*RH SIDE BRACKET RR BUMPER	Not Necessary	42.00 FN	*- FN
15	1		*LH STAY RR BUMPER	Bent	152.40 FN	*152.40 FN
16	1		*RH STAY RR BUMPER	Bent	152.40 FN	*152.40 FN
17	1		*REINFORCEMENT RR BUMPER	Dented	746.20 FN	*746.20 FN
18	1		*ENERGY ABSORBER RR BUMPER	Serviceable	168.10 FN	*- FN
19	1		*TOH COVER RR BUMPER	Not Necessary	22.40 FN	*- FN
20	1		*REAR BUMPER	Distorted	946.50 FN	*946.50 FN
21	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
22	1		*SENSOR REVERSE	Shorted	250.00 FS	*250.00 FS
23	1		*SUNDRIES	Repeated	50.00 FS	*- FS
24	1		*REAR LICENCE PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	5,840.80	2,979.60
- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,086.16	545.92
Total Parts (S\$)	4,754.64	2,433.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO REPAIR BOTH TAIL LAMP PANEL HATCH BACK DOOR AND BOTH RR FENDER ,RENEW RR END PANEL AND REAR BUMPER	New	1,680.00	1,000.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,500.00	750.00
3	APPLY SEALANT TO RR END PANEL	New	100.00	100.00
4	RENEW REVERSE SENSOR	New	110.00	110.00
5	RENEW RR BOTH RR COMB LAMP	New	48.00	48.00
6	COMPUTER CHECK DIAGNOSIS	New	180.00	0.00
7	TO REMOVE AND INSTALL BOTH RR FENDER INNER TRIM FINISHER	New	140.00	140.00
8	PERFORM RUSTPROOFING REAR END PANEL	New	120.00	120.00
Gross Labour Cost (\$\$)			3,878.00	2,268.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >