

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 3608D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	754.10	580.00
1	FRONT BUMPER REINFORCEMENT	BENT	474.70	322.00
1	FRONT BUMPER RH FOGLAMP	CRACKED	390.60	318.00
1	FRONT BUMPER RH FOGLAMP GARNISH	DEFORMED	150.10	150.10
2	FRONT BUMPER SIDE RETAINER L/R @\$129.90	O/S DAMAGED	259.80	55.00
1	FRONT BUMPER SPONGE	CRACKED	127.60	127.60
2	FRONT HEADLAMP L/R @\$766.10	O/S CRACKED	1,532.20	766.10
1	FRONT RH FENDER	BUCKLED	625.00	625.00
1	FRONT RH FENDER 'VVT-I' EMBLEM	NECESSARY	81.00	81.00
1	FRONT RH FENDER INNER BRACKET	BENT	98.00	98.00
1	FRONT RH FENDER INNER SHIELD	TORN	406.90	185.00
1	FRONT RH KNUCKLE ARM	BENT	703.70	441.00
1	FRONT RH KNUCKLE ARM BEARING	DAMAGED	248.90	248.90
1	FRONT RH LOWER ARM	BENT	596.00	596.00
1	FRONT RH SHOCK ABSORBER	BENT	647.80	322.00
1	FRONT RH SHOCK ABSORBER TOP MOUNTING	NOT NECESSARY	205.00	-
1	FRONT RH STABILIZER LINK	BENT	251.10	121.00
1	FRONT RH TIE ROD END	BENT	313.50	118.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,172.50	-
1	FRONT WASHER TANK	DEFORMED	177.10	107.00
2	FRONT WASHER TANK MOTOR @\$165.00	NOT NECESSARY	330.00	-
	LESS 25% DISCOUNT		-2,386.40	-1,315.42
			7,159.20	3,946.28
	SPECIAL NETT ITEMS			
1	FRONT RH 205/60R16 TYRE (SN)	NOT NECESSARY	480.00	-
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT RH SPORT RIM (SN)	CUT	850.00	400.00
			1,380.00	430.00

Report Ref No. CS/SMO23001922/Avy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REINSTALL AIR CON PARTS, VACUUMS, REFILL AIR CON GAS. (TO FR).	NOT NECESSARY	120.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSSING. (TO FR).		80.00	30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.		380.00	220.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.		100.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCCIDENT.		1,100.00	700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		800.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	40.00
			2,680.00	1,570.00
	GRAND TOTAL		11,219.20	5,946.28

RECOMMENDED COST OF LUMP SUM REPAIRS		4,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO23001922/Avy3m4



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.