

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 7066L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED/TORN	2,357.60	1,566.32
1	REAR BUMPER LOWER	DEFORMED	1,130.40	1,100.00
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	800.20	-
1	REAR BUMPER LOWER DIFFUSER (KIV)	CRACKED	1,100.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINERS @\$105.00	NOT NECESSARY	210.00	-
1	REAR BUMPER TOP RETAINER	CRACKED	188.20	188.20
1	REAR PDC SENSOR	SERVICEABLE	185.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	820.00	-
	LESS 5% DISCOUNT		-	-145.23
			6,841.40	2,759.29
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER WRAP STICKER (KIV) (SN)	NECESSARY	800.00	-
1	REAR LICENCE PLATE (SN)	SCRATCHED	50.00	40.00
			850.00	40.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	40.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM AND REAR END PANEL.		600.00	300.00
	TO PUTTY & SPRAY PAINTING.		680.00	600.00
			1,560.00	960.00
	GRAND TOTAL		9,251.40	3,759.29
		•		

Report Ref No. CS/AGI23001924/Uqy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI23001924/Uqy3m4

CHUA KANG SENG
Licensed Appraiser