

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	HSBC LIFE (SING		Ref:	CS3/HSB23001925/Rvp3e2
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	Date:	17/07/2023
	ATTN: LOW GARN	ET	Code:	HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SHB 9951R	Veh. Inspected	FBT 9879T
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S3M04IEG	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	21/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA AEROX GDR155A CVT	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	MH3SG731000001292	Colour	MULTI COLOUR
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	100/80-14	MAXXIS	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	110/80-14	MAXXIS	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S BODY.		
5. General Information				
	Accident Date	25/01/2023	Inspect Date / Time	22/02/2023 (12:02 PM)
	Survey held at	ROCKETRENTAL PTE LTD		
	5 SOON LEE STREET, #01-44, PIONEER POINT, SINGAPORE 627607			
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b.	Estimate Days of Repair			
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days		
	Report Ref No. CS3/HSB23001925/Rvp3e2			

Report Ref No. CS3/HSB23001925/Rvp3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser