

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123001930/AVY3M4**Date:** 05/05/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG22007792
Claimant Vehicle No :	SLP7140G	Insured Vehicle No :	SMM808P
Date of Loss:	20/02/2023	Nature of Claim:	TP
		Claim No:	CDMPG23000415

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7140G	Engine No:	L15B4411111
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11211111
Reg. Date:	15/06/2017 (Man. Year: 2016)	Odometer:	70812 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,364.48	5,053.76	9,310.72	64.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,620.00	2,030.00	2,590.00	56.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,984.48	7,083.76	11,900.72	62.69
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	18,984.48	5,600.00	13,384.48	70.50

INSPECTION

Date of Assignment:	21/02/2023	
Date Inspected:	22/02/2023	Inspected At: KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7140G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,723.20 FL	*1,100.00 FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	398.80 FL	*- FL
3	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
4	1		*TAILGATE BADGE	Not Necessary	98.60 FL	*- FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	95.70 FL	*70.00 FL
6	1		*TAILGATE LAMPS	N/S Cracked	997.40 FL	*425.00 FL
7	1		*TAILGATE LAMP INNER SEALER	Not Necessary	40.00 FL	*- FL
8	1		*SET TAILGATE LAMP CLIPS	Necessary	30.00 FL	*10.00 FL
9	2		*TAILGATE STOPPER	Not Necessary	50.00 FL	*- FL
10	1		*TAILGATE POCKET HANDLE	Not Necessary	65.80 FL	*- FL
11	1		*TAILGATE INNER TRIM	Cracked	485.60 FL	*285.00 FL
12	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	30.00 FL	*30.00 FL
13	1		*TAILGATE INNER LOCK	Damaged	345.80 FL	*182.00 FL
14	1		*TAILGATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Cut	198.70 FL	*198.70 FL
16	2		*TAILGATE HINGES	Not Necessary	136.00 FL	*- FL
17	2		*TAILGATE ABSORBERS	Not Necessary	397.20 FL	*- FL
18	1		*SET REAR WINDSCREEN MOULDING	Necessary	165.80 FL	*165.80 FL
19	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
20	1		*REAR WINDSCREEN	Not Necessary	698.70 FL	*- FL
21	1		*REAR BUMPER	Deformed	980.20 FL	*880.00 FL
22	1		*REAR BUMPER SIDE RETAINERS	Necessary	90.60 FL	*90.60 FL
23	1		*REAR BUMPER ATTACHMENT RETAINERS	Not Necessary	86.20 FL	*- FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
25	2		*REAR BUMPER REFLECTORS	Not Necessary	197.80 FL	*- FL
26	1		*REAR BUMPER UNDER COVER	Not Necessary	196.00 FL	*- FL
27	1		*SET REAR BUMPER UNDER COVER CLIPS	Not Necessary	30.00 FL	*- FL
28	1		*REAR CORNER BUMPER	O/S Deformed	611.20 FL	*195.00 FL
29	1		*END PANEL	Dented	595.00 FL	*595.00 FL
30	1		*END PANEL TOP TRIM	Deformed	198.30 FL	*198.30 FL
31	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*20.00 FL
32	1		*SPARE TYRE PANEL	Repair	1,245.00 FL	*- FL
33	1		*SPARE TYRE PANEL TOP BOARD	Deformed	462.00 FL	*306.00 FL
34	1		*SPARE TYRE PANEL TOP TOOL SPONGE	Cracked	351.00 FL	*285.00 FL
35	1		*REAR KEY ANTENA SENSOR	Cracked	145.80 FL	*145.80 FL
36	1		*ALARM SENSOR SPEAKER	Cracked	150.00 FL	*150.00 FL
37	1		*TAILLAMP	N/S Cracked	1,361.80 FL	*495.00 FL
38	1		*TAILLAMPS INNER SEALER	Not Necessary	40.00 FL	*- FL
39	1		*SET TAILLAMPS CLIPS	Not Necessary	30.00 FL	*- FL
40	2		*REAR FENDER INNER TRIM	Not Necessary	775.00 FL	*- FL
41	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FL	*- FL
42	2		*REAR FENDER INNER COWLING	Not Necessary	374.40 FL	*- FL
43	2		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FL	*- FL
44	2		*REAR FENDER ARCH GARNISH	Not Necessary	416.60 FL	*- FL
45	2		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
46	1		*REAR EXHAUST SILENCER	Not Necessary	897.30 FL	*- FL

Report was unsubmitted during this print-out.

5/5/23, 12:23 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*REAR EXHAUST MOUNTING	Not Necessary	92.00 FL	*- FL
48	1		*REAR EXHAUST GASKET	Not Necessary	48.00 FL	*- FL
49	1		*REAR EXHAUST HEAT PLATE	Not Necessary	145.60 FL	*- FL
50	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
51	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS
52	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
53	1		*SET REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
54	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
55	1		*SET IN -CAR CAMERA	Not Necessary	680.00 FS	*- FS
56	1		*REAR FLOOR PANEL INSULATOR PAD	Not Necessary	150.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					17,533.10	6,237.20
- List Item Discount on L Items 20.00/20.00% (S\$)					3,168.62	1,183.44
Total Parts (S\$)					14,364.48	5,053.76
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING	New	1,800.00	800.00
3	CHECK WIRING ON TAILAMP	New	120.00	30.00
4	ANTI RUST	New	120.00	60.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	120.00	60.00
7	REMOVE AND INSTALL INTERIOR UPHOLSTERY	New	150.00	60.00
8	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	50.00
9	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
10	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (\$\$)			4,620.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >