

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III23001933/UNY3Q2**Date:** 23/03/2023**REFERENCE**

Insured/Claimant: THNG CHYE TECK Policy No: D18MPC0002380_04
Date of Loss: 18/02/2023 Nature of Claim: OD Claim No: MPC2023D0002471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH9151D**
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR1857171
Reg. Date: 23/11/2016 (Man. Year: 2016) Chassis No: JTDGG20W40J005979
Colour: Orange Odometer: 69229 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,638.92	7,549.41	2,089.51	21.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,770.00	1,350.00	43.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,758.92	9,319.41	3,439.51	26.96
Approved Total (Overridden) (\$\$)		7,400.00		
- Excess (\$\$)	750.00	750.00	0.00	0.00
(\$\$)	12,008.92	6,650.00	5,358.92	44.62
+ GST 8.00/8.00% (\$\$)	960.71	532.00	428.71	44.62
Nett Amount (\$\$)	12,969.63	7,182.00	5,787.63	44.62

INSPECTION

Date of Assignment: 21/02/2023

Date Inspected: 22/02/2023

Inspected At:

Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH9151D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	781.45 FL	*781.45 FL
2	2		*BONNET HINGES	Bent	242.70 FL	*242.70 FL
3	1		*BONNET LOCK	Twisted	182.10 FL	*182.10 FL
4	1		*BONNET LOCK CABLE	Not Necessary	177.45 FL	*- FL
5	2		*BONNET STOPPER	Not Necessary	87.50 FL	*- FL
6	1		*BONNET BADGE	Necessary	61.10 FL	*61.10 FL
7	1		*BONNET INNER RUBBER BEADING	Necessary	132.10 FL	*132.10 FL
8	14		*BONNET INSULATOR CLIPS	Not Necessary	180.60 FL	*- FL
9	1		*BONNET LOCK BRACE PANEL	Bent	186.60 FL	*186.60 FL
10	2		*HEAD LAMP -HID	Holder Cracked	3,634.40 FL	*3,230.60 FL
11	2		*HEAD LAMP CLIPS	Not Necessary	25.80 FL	*- FL
12	1		*FRONT BUMPER FASCIA	Torn	481.10 FL	*481.10 FL
13	1		*FRONT BUMPER SIDE RETAINER	N/S Bent	110.40 FL	*55.20 FL
14	1		*FRONT BUMPER SPONGE	Torn	161.60 FL	*161.60 FL
15	1		*FRONT BUMPER REINFORCEMENT	Bent	387.75 FL	*387.75 FL
16	1		*SET FRONT BUMPER CLIPS	Necessary	129.00 FL	*50.00 FL
17	1		*FRONT GRILLE	Cracked	147.20 FL	*147.20 FL
18	1		*SET FRONT GRILLE CLIPS	Necessary	51.60 FL	*30.00 FL
19	2		*HORN ASSY	Not Necessary	470.20 FL	*- FL
20	1		*FOG LAMP ASSY -LH	Not Necessary	281.90 FL	*- FL
21	1		*FOG LAMP COVER -INNER LH	Not Necessary	132.10 FL	*- FL
22	1		*FOG LAMP SIDE AIR GRILLE GARNISH -LH	Not Necessary	181.90 FL	*- FL
23	1		*FRONT SUPPORT PANEL	Bent / Twisted	972.25 FL	*972.25 FL
24	1		*FRONT SUPPORT PANEL TOP GARNISH	Twisted	281.90 FL	*281.90 FL
25	2		*AIR COND CONDENSOR SIDE AIR GRILLE GARNISH	Not Necessary	364.50 FL	*- FL
26	1		*AIR COND CONDENSOR	Bent / Punctured	1,218.45 FL	*1,218.45 FL
27	2		*AIR COND CONDENSOR TOP MOUNTING	Not Necessary	242.20 FL	*- FL
28	2		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	25.80 FL	*- FL
29	1		*RADIATOR ASSY	Bent / Punctured	972.45 FL	*972.45 FL
30	1		*RADIATOR TOP GARNISH	Cracked	287.10 FL	*287.10 FL
31	1		*RADIATOR TOP MOUNTING	N/S Not Necessary / O/S Bent	59.60 FL	*29.80 FL
32	1		*BATTERY BRACKET	Bent	121.10 FL	*121.10 FL
33	1		*FRONT NUMBER PLATE WITH CASING	Bent	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,831.90	10,052.55
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,192.98	2,503.14
Total Parts (\$\$)	9,638.92	7,549.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	80.00	50.00
2	TO CHECK WIRING SYSTEM	New	80.00	20.00
3	TO RESPRAY AFFECTED AREAS	New	1,400.00	800.00
4	TO RENEW DAMAGED PARTS ,STRAIGHTEN AND REPAIR & ALIGNED ALL PARTS	New	1,000.00	800.00
5	TO REMOVE & REFIX RADIATOR & TOP UP COOLANT	New	280.00	0.00
6	TO REMOVE & REFIX AIR COND CONDENSOR, VACUUM AND TOP UP GAS	New	280.00	100.00
Gross Labour Cost (S\$)			3,120.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >