

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC23001947/Uvy3e2
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date:	06/06/2023
	ATTN: HELENA TA	N.	Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	FBD 8557M	Veh. Inspected	SLS 668G
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1204484-003	Excess (\$)	0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	21/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A5 SB (A)	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WAUZZZF52JA028699	Colour	RED
	Odometer	68936 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/35Z R19	MICHELIN	7 mm
	L/H Front Tyre	255/35Z R19	MICHELIN	7 mm
	R/H Rear Tyre	255/35Z R19	MICHELIN	7 mm
	L/H Rear Tyre	255/35Z R19	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO		
5.	General Information			
	Accident Date	06/01/2023	Inspect Date / Time	21/02/2023 (10:11 AM)
	Survey held at	15 Kaki Bukit Road 4, Bartley Biz	Z Centre, #01-53	
	Repairer	ZOOM AUTOWERKS PTE LTD		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/INC23001947/Uvy3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser