

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23001959/HNY3M4**Date:** 30/03/2023**REFERENCE**

Insured/Claimant:	TAN BEE LING ANNIE	Policy No:	SP2001203659	
Date of Loss:	17/02/2023	Nature of Claim:	OD	Claim No: 202332005577

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EV9922E		
Make & Model:	VOLVO S60, 2.0 T4 (M)	Engine No:	B4204T443109013
Reg. Date:	25/02/2020 (Man. Year: 2019)	Chassis No:	7JRZSALADLG032274
Colour:	Black	Odometer:	43677 km
Engine Capacity:	1969 cc		
Market Value/New Car Price:	S\$124,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,435.70	6,666.09	769.61	10.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,660.00	5,700.00	1,960.00	25.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,095.70	12,366.09	2,729.61	18.08
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	14,495.70	11,766.09	2,729.61	18.83
+ GST 8.00/8.00% (\$\$)	1,159.66	941.29	218.37	18.83
Nett Amount (\$\$)	15,655.36	12,707.38	2,947.98	18.83

INSPECTION

Date of Assignment:	22/02/2023	
Date Inspected:	22/02/2023	Inspected At: Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road Singapore 159935
Estimated Period of Repair:	5.0 days	

Adjuster: Edward**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	143	VOLVO S60 2.0 T4 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EV9922E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE INCLUDE HOLDER	Cracked	60.00 FS	*60.00 FS
2	1		*BRACKET LH BONNET SV	Necessary	262.90 FS	*236.61 FS
3	1		*BRACKET RH BONNET SV	Necessary	262.90 FS	*236.61 FS
4	1		*BONNET HINGE LH SV60	Bent	343.00 FS	*308.70 FS
5	1		*BONNET HINGE RH SV60	Bent	343.00 FS	*308.70 FS
6	1		*HOOD HINGE RELEASE	Necessary	338.60 FS	*304.74 FS
7	1		*HOOD HINGE RELEASE	Necessary	338.60 FS	*304.74 FS
8	1		*DECAL, AC, ENGLISH T	Not Necessary	35.60 FS	*- FS
9	1		*CONTROL UNIT SRS S60	Necessary	2,009.00 FS	*1,808.10 FS
10	1		*NUMBER PLATE RETAINE	Cracked	78.00 FS	*70.20 FS
11	1		*BUMPER GRILLE LOWER	Cracked	165.90 FS	*149.31 FS
12	1		*BONNET FRT SV60 20-	Bent	3,162.60 FS	*2,846.34 FS
13	1		*DECAL, AC, ENGLISH T	Necessary	35.60 FS	*32.04 FS
					F=Franchise part. S=SpcNett.	
					Total Parts (S\$)	7,435.70 6,666.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER GRILLE,FRT BONNET HINGES, FRT BONNET, ETC	New	2,550.00	1,700.00
2	TO PUTTY SPRAY PAINT ON FRT BONNET HINGES,ETC	New	750.00	400.00
3	TO REPLACE FRONT BONNET AIR BA INCLUDE PROGRAMMING	New	3,040.00	2,280.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	570.00	570.00
5	TO PUTTY SPRAY PAINT ON FRT BONNET	New	750.00	750.00
Gross Labour Cost (\$\$)			7,660.00	5,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >