

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23001963/SQY3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR004253
Claimant Vehicle No :	SHD3332G	Insured Vehicle No :	SKR3909J
Date of Loss:	17/02/2023	Nature of Claim:	TP
		Claim No:	M2301155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3332G		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4DFU596605
Reg. Date:	21/07/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU092145
Colour:	Blue	Odometer:	959672 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,122.16	642.40	479.76	42.75
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	980.00	590.00	390.00	39.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,113.16	1,243.40	869.76	41.16
Approved Total (Overridden) (\$\$)		1,000.00		
(\$\$)	2,113.16	1,000.00	1,113.16	52.68
+ GST 8.00/8.00% (\$\$)	169.05	80.00	89.05	52.68
Nett Amount (\$\$)	2,282.21	1,080.00	1,202.21	52.68

INSPECTION

Date of Assignment:	21/02/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/02/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3332G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Broken	553.00 FL	*553.00 FL
2	1		*REAR BUMPER LOWER COVER	Scratched	228.00 FL	*228.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	*- FL
4	1		*REAR BUMPER BRACKET RH	Not Necessary	35.60 FL	*- FL
5	10		*REAR BUMPER BRACKET CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR REVERSE SENSOR	Not Necessary	135.70 FL	*- FL
					Sub Total (S\$)	1,402.70
					- List Item Discount on L Items 20.00/20.00% (S\$)	280.54
					Total Parts (S\$)	1,122.16

F=Franchise part. L=ListItemDisc.

803.00

160.60

642.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	560.00	280.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOV/REFIX REVERSE SENSOR	New	60.00	30.00
4	CHECK WIRING AND LIGHTING	New	60.00	30.00
Gross Labour Cost (\$\$)			980.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >