

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001966/KVP3Q2**Date:** 08/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00086302213
Claimant Vehicle No :	SLR4530Z	Insured Vehicle No :	GZ6869B
Date of Loss:	16/02/2023	Nature of Claim: TP	Claim No: SNM23D201287/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR4530Z		
Make & Model:	KIA NIRO HYBRID, 1.6 DCT SUNROOF (A)	Engine No:	G4LEHS216271
Reg. Date:	16/08/2017 (Man. Year: 2017)	Chassis No:	KNACC81CVJ5096605
Colour:	Metallic Red	Odometer:	87035 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,393.80	2,279.70	2,114.10	48.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	980.00	1,340.00	57.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,713.80	3,259.70	3,454.10	51.45
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	6,713.80	2,600.00	4,113.80	61.27
+ GST 8.00/8.00% (S\$)	537.10	208.00	329.10	61.27
Nett Amount (S\$)	7,250.90	2,808.00	4,442.90	61.27

INSPECTION

Date of Assignment:	22/02/2023	
Date Inspected:	08/03/2023 Inspected At:	T & B Motor Repairs Services Pte Ltd Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2023)
Parts:	M1-SUV	KIA NIRO HYBRID 1.6 DCT SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR4530Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER R/H	Bent	635.00 FL	*635.00 FL
2	1		*FRONT FENDER SIDE GARNISH RH	Distorted / Cut	145.00 FL	*145.00 FL
3	1		*FRONT FENDER INNER SHIELD RH	Serviceable	145.00 FL	*- FL
4	10		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	35.00 FL	*- FL
5	1		*FRONT HEADLAMP RH	Mtg Cracked	1,375.00 FL	*904.00 FL
6	1		*FRONT BUMPER	Deep Cut	835.00 FL	*688.00 FL
7	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	48.00 FL	*48.00 FL
9	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	48.00 FL	*- FL
10	1		*FRONT GRILLE	Serviceable	550.00 FL	*- FL
11	1		*SIDE MIRROR R/H (AUTO)	Respray	953.00 FL	*- FL
12	1		*FRONT BUMPER (KIA) (LOGO)	Necessary	78.00 FL	*78.00 FL
					Sub Total (\$\$)	4,882.00 2,533.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	488.20 253.30
					Total Parts (\$\$)	4,393.80 2,279.70

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE OF NEW SIDE MIRROR PART	New	150.00	0.00
2	CHECK & REPAIR WIRING	New	120.00	20.00
3	SPRAY ANTI-RUST COATING	New	150.00	30.00
4	SPRAY PAINT ON AFFECTED PORTIONS	New	900.00	450.00
5	LABOUR CHARGE FOR REPAIRING ,ADJUSTING ,KNOCKING,WELDING THE DAMAGED PARTS ,STRAIGHTEN THE ABOVE	New	1,000.00	480.00
Gross Labour Cost (\$\$)			2,320.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >