

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23001967/RQY3Q2**Date:** 18/04/2023**REFERENCE**

Insured/Claimant: WALLS MICHAEL RICHARD PATRICK
Date of Loss: 04/02/2023

Policy No: SP2002854049-01
Nature of Claim: OD

Claim No: 202332005545

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV2226H**
Make & Model: VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ (A) Engine No: CZDA48471
Reg. Date: 22/09/2020 (Man. Year: 2019) Chassis No: WVGZZZ1TZKW072903
Colour: Blue Odometer: 24979 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$142,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,968.35	4,927.66	40.69	0.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,220.00	5,480.00	2,740.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,188.35	10,407.66	2,780.69	21.08
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,588.35	9,807.66	2,780.69	22.09
+ GST 8.00/8.00% (S\$)	1,007.07	784.61	222.46	22.09
Nett Amount (S\$)	13,595.42	10,592.27	3,003.15	22.09

INSPECTION

Date of Assignment: 22/02/2023

Date Inspected: 27/02/2023 Inspected At:

Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 1.4 TSI CL 5T13NZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV2226H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR LHS FRT DOOR	Bent	2,061.87 FS	*2,061.87 FS
2	1		*DOOR SEAL OUTER BLACK	Necessary	154.96 FS	*154.96 FS
3	1		*ALU-LAMIN INSUTION DOOR INSULATOR	Necessary	31.44 FS	*31.44 FS
4	2		*BOLT WITH POLYGON SOCKET	Necessary	8.22 FS	*8.22 FS
5	1		*FILL ,HD.SCREW (2 PCS)	Necessary	4.49 FS	*4.49 FS
6	1		*DOOR HANDLE OUTER PRIMED	Scratched	187.86 FS	*187.86 FS
7	1		*HOUSING	Scratched	23.82 FS	*23.82 FS
8	1		*COVER FOR DOOR LOCK PRIME	Scratched	16.65 FS	*16.65 FS
9	1		*BOW SPPOR DOOR HANDLE	Cracked	100.86 FS	*100.86 FS
10	1		*GROMMET (2 PCS)	Necessary	2.71 FS	*2.71 FS
11	1		*FELT STRIP	Necessary	17.40 FS	*17.40 FS
12	1		*DOOR LHS REAR DOOR	Bent	2,061.87 FS	*2,061.87 FS
13	1		*DOOR SEAL OUTER BLACK	Necessary	182.35 FS	*182.35 FS
14	1		*ALU-LAMIN INSULATION DOOR INSULATOR	Necessary	31.44 FS	*31.44 FS
15	1		*HEX BOLT WITH INTERNAL TO (2 PCS)	Necessary	5.95 FS	*5.95 FS
16	1		*FILL HD .SCREW (2 PCS)	Necessary	4.49 FS	*4.49 FS
17	1		*STONE PROTECTION FOIL LHR FENDER FOIL	Necessary	31.28 FS	*31.28 FS
18	1		*GUIDE PIECE LHR BUMPER SIDE BRACKET	Not Necessary	40.69 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	4,968.35 4,927.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	LABOUR	New	3,360.00	2,240.00
4	SPRAY PAINT	New	3,180.00	2,120.00
5	TRANSFER DOOR MECHAISM	New	1,120.00	560.00
Gross Labour Cost (S\$)			8,220.00	5,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >