

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001970/RQP3E2**Date:** 04/07/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00141092205
<b>Claimant Vehicle No :</b>	SNF8037U	<b>Insured Vehicle No :</b>	SKN4947M
Date of Loss:	21/02/2023	Nature of Claim:	TP
		Claim No:	SNM23D201383/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNF8037U</b>	Engine No:	37686748B38A15A
Make & Model:	BMW 216I, 1.5 (A)	Chassis No:	WBA32AN0207K92941
Reg. Date:	23/06/2022 (Man. Year: 2022)	Odometer:	9744 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,142.15	4,810.50	4,331.65	47.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,148.00	13,141.00	5,007.00	27.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>27,290.15</b>	<b>17,951.50</b>	<b>9,338.65</b>	<b>34.22</b>
<b>+ GST 8.00/8.00% (S\$)</b>	2,183.21	1,436.12	747.09	34.22
<b>Nett Amount (S\$)</b>	<b>29,473.36</b>	<b>19,387.62</b>	<b>10,085.74</b>	<b>34.22</b>

INSPECTION

Date of Assignment:	22/02/2023	
Date Inspected:	13/03/2023 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	11.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2023)
<b>Parts:</b>	M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNF8037U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*SPRING STRUT	Not Necessary	252.10 FS	*- FS
3	1		*ALLOY RIM 7.5X17 DOUBLE SPK 549	Scratched	977.35 FS	*977.35 FS
4	1		*LH C PILLAR REINFORCEMENT PLATE	Not Necessary	82.20 FS	*- FS
5	1		*LH D PILLAR REINFORCEMENT PLATE	Not Necessary	79.30 FS	*- FS
6	1		*REINFORCEMENT PLATE UNIVERSAL	Not Necessary	55.30 FS	*- FS
7	1		*REAR LH SIDE PANEL	Not Necessary	1,540.95 FS	*- FS
8	1		*FRT LH DOOR	Bent	1,194.55 FS	*1,194.55 FS
9	1		*REAR LH DOOR	Bent	1,194.55 FS	*1,194.55 FS
10	1		*LH OUTSIDE MIRROR HEATED WITH MEMOR	Cracked	859.90 FS	*859.90 FS
11	1		*LH OUTSIDE MIRROR COVER CAP PRIMED	Cracked	133.90 FS	*133.90 FS
12	1		*STRIKER WITHOUT SHIM	Not Necessary	26.50 FS	*- FS
13	1		*ACOUSTIC COVER REAR LEFT	Not Necessary	68.60 FS	*- FS
14	1		*LH DOOR OUTSIDE HANDLE CARRIER CA	Repair	349.75 FS	*- FS
15	1		*REAR LH SYSTEM LOCK	Not Necessary	303.85 FS	*- FS
16	1		*REAR LH WINDOW LIFTER W/O MOTOR	Not Necessary	347.75 FS	*- FS
17	2		*(S/L) DOOR WEATHERSTRIP	Necessary	286.60 FS	*286.60 FS
18	1		*FRT DOOR EDGE PROTECTION	Not Necessary	172.50 FS	*- FS
19	1		*REAR DOOR EDGE PROTECTION	Not Necessary	172.50 FS	*- FS
20	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Not Necessary	125.60 FS	*- FS
21	2		*(DG) CLEANER R1 (100ML)	Not Necessary	52.30 FS	*- FS
22	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
23	20		*PUNCH RIVET N4	Not Necessary	11.00 FS	*- FS
24	1		*(DG/SL) BODY ADHESIVE K5 (195 ML)	Not Necessary	364.15 FS	*- FS
25	2		*(SL/SG) SEALANT D2 290ML	Not Necessary	64.20 FS	*- FS
26	7		*CLIP ROOF FRAME STRIP	Necessary	13.65 FS	*13.65 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)** **9,142.15** **4,810.50**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR LEFT FENDER, REAR LEFT DOOR, FRONT LEFT DOOR, MAKE GOOD REAR BUMPER AND LEFT SIDE SILL TRIM	New	6,800.00	5,525.00
2	TO RESPRAY REAR LEFT FENDER, REAR LEFT DOOR, FRONT LEFT DOOR, LEFT SIDE SILL TRIM, C PILLAR, LEFT SIDE MIRROR COVER, DOOR HANDLE 2X AND AFFECTED AREAS	New	5,484.00	5,209.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	0.00
4	TO CARRY OUT BODY CAVITY PRESERVATION. 3X (PER PANEL)	New	354.00	224.00
5	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS. (1X)	New	531.00	504.00
7	TO REPLACE REAR LEFT PNEUMATIC SPRING STRUT INCLUDING RESET AND CHECK FUNCTION FOR RIDE LEVEL HEIGHT CONTROL FOR PROPER FUNCTION	New	885.00	0.00
8	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X)	New	94.00	90.00
9	TO CONDUCT CHASSIS ALIGNMENT MEASURING CHECK USING CAR-O-LINER MEASURING SYSTEM ACCORDANCE WITH BMW SPECIFICATION	New	531.00	0.00
10	TO REMOVE AND INSTALL DOOR FIXED WINDOW GLASS TO FACILITATE REPAIR	New	574.00	338.00
11	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
12	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIR	New	873.00	0.00
13	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION. (2 DOORS)	New	1,062.00	1,008.00
14	TO CHECK ELECTRICAL	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>18,148.00</b>	<b>13,141.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >