

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 1242A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR LHS	TO REPAIR SEE LABOUR	1,050.00	-
1	ROCKER PANEL LHS	TO REPAIR SEE LABOUR	400.00	-
1	REAR FENDER LHS	TO REPAIR SEE LABOUR	990.00	-
1	REAR FENDER INNER SHIELD LHS	SERVICEABLE	80.00	-
1	REAR BUMPER	SERVICEABLE	550.00	-
	LESS 25% DISCOUNT		-767.50	-
			2,302.50	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR DOOR LHS, ROCKER PANEL LHS AND REAR FENDER LHS.		1,600.00	300.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,600.00	750.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.	NOT NECESSARY	100.00	-
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
	DIAGNOSTIC CHECK.	NOT NECESSARY	100.00	-
	ALIGNMENT CHECK.		100.00	60.00
			3,600.00	1,110.00
	GRAND TOTAL		5,962.50	1,110.00

Report Ref No. CS/SPF23001971/Kny3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			1,110.00
-----------------------------	--	--	----------

Report Ref No. CS/SPF23001971/Kny3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$1,500

KONG SENG CHEONG

Licensed Appraiser