

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 5701Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR O/S DOOR	BENT	1,122.70	1,122.70
1	REAR O/S DOOR OUTER HANDLE	DISTORTED	78.70	78.70
1	REAR O/S DOOR RUBBER	SERVICEABLE	215.00	-
1	REAR O/S DOOR INNER LOCK	DENTED/JAMMED	592.80	592.80
1	REAR O/S DOOR PROTECTOR	BENT	109.90	109.90
1	O/S DOOR PROTECTOR CHROME	NECESSARY	26.90	26.90
1	REAR O/S DOOR GLASS REGULATOR GEAR	DISTORTED	194.80	194.80
1	REAR O/S DOOR GLASS REGULATOR MOTOR	JAMMED	765.50	765.50
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,250.20	-
1	REAR W/S GLASS MOULDING	NOT NECESSARY	97.40	-
1	O/S SIDE SKIRT	CRACKED	368.80	368.80
	LESS 25% DISCOUNT		-1,205.68	-815.02
			3,617.02	2,445.08
	SPECIAL NETT ITEMS			
1	REAR W/S GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NOT NECESSARY	150.00	-
	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.		120.00	60.00
	TO APPLY UNDERSEALING.		60.00	30.00
	TO PUTTY AND SPRAY REPLACED PARTS.		700.00	500.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR O/S FENDER.		800.00	680.00
			1,830.00	1,270.00
	GRAND TOTAL		5,507.02	3,715.08

Report Ref No. CS/FCI23001972/Kny3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,950.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI23001972/Kny3m4

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$19,715.00=NETT VALUE: \$25,285.00

KONG SENG CHEONG

Licensed Appraiser