

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123001973/SNP3E2**Date:** 21/07/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00140092202

**Claimant Vehicle
No :** SKQ5731X**Insured Vehicle
No :** GBG6677Y

Date of Loss: 16/02/2023

Nature of Claim: TP

Claim
No: SNM23D201288/C02/TOHHSDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKQ5731X**

Make & Model: VOLKSWAGEN JETTA, 1.4 TSI (A)

Engine No: CAXE89317

Reg. Date: 10/12/2014 (Man. Year: 2014)

Chassis No: WVVZZZ16ZEM063597

Colour: Blue

Odometer: 114841 km

Engine Capacity: 1390 cc

Market Value/New Car
Price: N/ASum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,444.20	3,069.80	7,374.40	70.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	900.00	2,770.00	75.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,114.20	3,969.80	10,144.40	71.87
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	14,114.20	3,200.00	10,914.20	77.33
+ GST 8.00/8.00% (S\$)	1,129.14	256.00	873.14	77.33
Nett Amount (S\$)	15,243.34	3,456.00	11,787.34	77.33

INSPECTION

Date of Assignment: 23/02/2023

Date Inspected: 23/02/2023 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2023)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ5731X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,973.00 FL	*- FL
2	1		*BOOTLID CENTRE EMBLEM	Not Necessary	97.00 FL	*- FL
3	1		*BOOTLID JETTA EMBLEM	Not Necessary	68.00 FL	*- FL
4	1		*BOOTLID TSI EMBLEM	Not Necessary	59.00 FL	*- FL
5	1		*BOOTLID RH LAMP	Not Necessary	286.00 FL	*- FL
6	1		*BOOTLID LH LAMP	Not Necessary	286.00 FL	*- FL
7	1		*BOOTLID LOCK	Not Necessary	201.00 FL	*- FL
8	1		*BOOTLID INNER TRIM	Not Necessary	268.00 FL	*- FL
9	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	80.00 FL	*- FL
10	1		*REAR BUMPER	Cracked	1,276.00 FL	*1,276.00 FL
11	1		*REAR BUMPER TOW COVER	Not Necessary	34.00 FL	*- FL
12	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
13	1		*REAR BUMPER LOWER SKIRT	Cracked	489.00 FL	*489.00 FL
14	1		*REAR BUMPER RH REFLECTOR	Not Necessary	73.00 FL	*- FL
15	1		*REAR BUMPER LH REFLECTOR	Not Necessary	73.00 FL	*- FL
16	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	86.00 FL	*- FL
17	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	86.00 FL	*- FL
18	1		*REAR BUMPER CENTRE BRACKET	Cracked	83.00 FL	*83.00 FL
19	1		*REAR BUMPER RH SIDE ATTACHMENT	Not Necessary	87.00 FL	*- FL
20	1		*REAR BUMPER LH SIDE ATTACHMENT	Not Necessary	87.00 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Not Necessary	621.00 FL	*- FL
22	1		*REAR BUMPER LOWER COVER	Missing	93.00 FL	*38.00 FL
23	1		*END PANEL	Dented	1,299.00 FL	*1,206.00 FL
24	1		*END PANEL INNER GARNISH	Not Necessary	167.00 FL	*- FL
25	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
26	1		*RH TAILLAMP ASSY	Not Necessary	505.00 FL	*- FL
27	1		*RH TAILLAMP LOWER BRACKET	Not Necessary	65.00 FL	*- FL
28	1		*LH TAILLAMP ASSY	Not Necessary	505.00 FL	*- FL
29	1		*LH TAILLAMP LOWER BRACKET	Not Necessary	65.00 FL	*- FL
30	1		*REAR RH FENDER INNER TRIM	Not Necessary	187.00 FL	*- FL
31	1		*SET REAR RH FENDER INNER TRIM CLIPS	Not Necessary	70.00 FL	*- FL
32	1		*REAR LH FENDER INNER TRIM	Not Necessary	187.00 FL	*- FL
33	1		*SET REAR LH FENDER INNER TRIM CLIPS	Not Necessary	70.00 FL	*- FL
34	1		*SPARE TYRE PANEL UPPER COVER BOARD	Not Necessary	376.00 FL	*- FL
35	1		*EXHAUST SILENCER	Not Necessary	953.00 FL	*- FL
36	1		*EXHAUST SILENCER GASKET	Not Necessary	43.00 FL	*- FL
37	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
38	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*60.00 FS
39	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,548.00 3,382.00

- List Item Discount on L Items 10.00/10.00% (\$\$) 1,103.80 312.20

Report was unsubmitted during this print-out.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	400.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,300.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	40.00
5	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	120.00	0.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
7	REMOVE AND REPLACE REAR INNER TRIMS AND GARNISH TO ASSIST REPAIR	New	220.00	0.00
8	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	150.00	0.00
9	REMOVE AND REINSTALL BOOTLID REVERSE CAMERA TO ASSIST REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			3,670.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >