

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 7128Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER R/H (CONSISTENT)	DENTED / BENT	861.00	861.00
1	FRONT FENDER CHROME MOULDING R/H (CONSISTENT)	NECESSARY	112.00	112.00
1	FRONT DOOR R/H (CONSISTENT)	DENTED / BENT	1,685.00	1,685.00
1	FRONT DOOR CHROME MOULDING R/H (CONSISTENT)	NECESSARY	198.00	198.00
1	FRONT DOOR INNER RUBBER R/H (CONSISTENT)	NECESSARY	266.00	266.00
1	REAR DOOR R/H (CONSISTENT)	TO REPAIR SEE LABOUR	1,655.00	-
1	REAR DOOR CHROME MOULDING R/H (CONSISTENT)	NECESSARY	198.00	198.00
1	FRONT SPORT RIM R/H (CONSISTENT)	NOT NECESSARY	800.00	-
1	FRONT DOOR MIRROR R/H (CONSISTENT)	TO REPAIR SEE LABOUR	600.00	-
1	FRONT WHEEL BEARING (CONSISTENT)	NOT NECESSARY	400.00	-
	LESS 10% DISCOUNT		-677.50	-332.00
			6,097.50	2,988.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR R/H AND FRONT DOOR MIRROR R/H. }		1,500.00	500.00
	LABOUR CHARGES. }		150.00	-
	TO RESPRAY REPLACED AND AFFECTED PANEL.		1,600.00	800.00
	TO CARRY OUT ANTI RUST TREATMENT.		180.00	60.00
	TO CHECK WIRING FOR PROPER FUNCTION.		100.00	20.00
	TO CARRY OUT WHEEL ALIGNMENT.		120.00	60.00
			3,650.00	1,440.00
	GRAND TOTAL		9,747.50	4,428.00

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/HSB23001981/Uvp3e2

**CHUA KANG SENG** 

**Licensed Appraiser**