

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR23001986/Wqy3e2	
	60 WOODLANDS I E4SINGAPORE 75		Date:	28/02/2023		
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHF 181J	Veh. Inspected	k	FBM 7502E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/02/23/2047	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		22/02/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA FS150F	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	PMKKC27A0JB106713	Colour		ORANGE	
	Odometer	69567 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	90/80-17	MAXXIS		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70-17	MAXXIS		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSBODY.	JSTAINED DAMAGES AT THE FRONT PORTION AND N/S				
5.	General Information					
	Accident Date	17/02/2023	Inspect Date /	Time	22/02/2023 ( 03:55 PM )	
	Survey held at	464 Macpherson Road Singapore 368182				
	Repairer	pairer MOTO 51 PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,400-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/SMR23001986/Wqy3e2

Inspected By

**Asst. Automotive Assessor** 

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser