

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23001988/KNY3Q2**Date:** 03/05/2023**REFERENCE**

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SHF622D **Insured Vehicle No :** SLU5177M

Date of Loss: 20/02/2023 Nature of Claim: TP Claim No: DMPC2300115H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF622D**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G96687

Reg. Date: 30/09/2020 (Man. Year: 2020) Chassis No: JTDKB3FUX03092070

Colour: Metallic Pearl White/Red Odometer: 258277 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Wanli 9 mm Rear Left Side: Wanli 9 mm

Front Right Side: Wanli 9 mm Rear Right Side: Wanli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,585.12	4,267.23	4,317.89	50.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,610.00	1,700.00	5,910.00	77.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,195.12	5,967.23	10,227.89	63.15
+ GST 8.00/8.00% (S\$)	1,295.61	477.38	818.23	63.15
Nett Amount (S\$)	17,490.73	6,444.61	11,046.12	63.15

INSPECTION

Date of Assignment: 22/02/2023

Date Inspected: 22/02/2023 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount:\$5,967.24

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF622D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	612.68 FL	*612.68 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	419.90 FL	*419.90 FL
3	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	167.48 FL	*- FL
4	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	167.48 FL	*- FL
5	1		*COVER ,REAR BUMPER ,LOWER	Dented	27.93 FL	*27.93 FL
6	1		*GUARD ,REAR BUMPER CENTER	Bent	472.19 FL	*472.19 FL
7	1		*REFLECTOR ASSY ,REFLEX,LH	Serviceable	49.25 FL	*- FL
8	1		*REFLECTOR ASSY ,REFLEX,RH	Serviceable	49.25 FL	*- FL
9	1		*LENS & BODY REAR COMBINATION LAMP ,LH	Serviceable	428.19 FL	*- FL
10	1		*LENS & BODY REAR COMBINATION LAMP NO.2 LH	Serviceable	329.49 FL	*- FL
11	1		*COVER ,REAR COMBINATION LAMP ,LH	Serviceable	88.41 FL	*- FL
12	1		*COVER ,FLOOR UNDER NO.1 LH	Serviceable	220.50 FL	*- FL
13	1		*COVER ,FLOOR UNDER NO.2 RH	Serviceable	304.92 FL	*- FL
14	1		*COVER ,REAR FLOOR CTR	Cracked	290.43 FL	*290.43 FL
15	1		*COVER ,DECK TRIM ,REAR	Serviceable	159.39 FL	*- FL
16	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	824.46 FL	*- FL
17	1		*PANEL SUB-ASSY ,BACK DOOR	Buckled	1,443.86 FL	*1,443.86 FL
18	1		*WEATHERSTRIP ,BACK DOOR	Serviceable	469.25 FL	*- FL
19	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Mtg Cracked	1,156.89 FL	*1,156.89 FL
20	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	326.76 FL	*- FL
21	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	305.66 FL	*- FL
22	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	305.66 FL	*- FL
23	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	77.18 FL	*- FL
24	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	77.18 FL	*- FL
25	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Necessary	68.88 FL	*68.88 FL
26	1		*PLATE ,BACK DOOR NAME NO.1	Necessary	68.88 FL	*68.88 FL
27	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	90.30 FL	*90.30 FL
28	1		*ANTENNA ELECTRIC SENSOR	Dirt	91.04 FL	*91.04 FL
29	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
30	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	*200.00 FS
31	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS
32	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
33	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
34	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
35	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
36	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
37	1		*SET PARKING AID	Dented	700.00 FS	*250.00 FS
38	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,858.49	5,452.98
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,273.37	1,185.75
Total Parts (\$\$)	8,585.12	4,267.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	600.00
3	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
5	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	880.00
9	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
13	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			7,610.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >