

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123001995/KNY3Q2**Date:** 18/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMZ5812A **Insured Vehicle No :** GBJ8433E

Date of Loss: 18/02/2023 Nature of Claim: TP Claim No: CDMCG23000426

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ5812A**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B5582621

Reg. Date: 03/05/2021 (Man. Year: 2020) Chassis No: RU11332580

Colour: Metallic Grey Odometer: 109058 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Airvo 7 mm Rear Left Side: Dunlop 3 mm

Front Right Side: Airvo 7 mm Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,868.16	7,897.32	4,970.84	38.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,450.00	770.00	34.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,088.16	9,347.32	5,740.84	38.05
Approved Total (Overridden) (S\$)		7,450.00		
(S\$)	15,088.16	7,450.00	7,638.16	50.62
+ GST 8.00/8.00% (S\$)	1,207.05	596.00	611.05	50.62
Nett Amount (S\$)	16,295.21	8,046.00	8,249.21	50.62

INSPECTION

Date of Assignment: 22/02/2023

Date Inspected: 01/03/2023 Inspected At: Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming AutoCare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ5812A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,125.00 FL	*892.10 FL
2	2		*FRONT BONNET HINGE	Distorted	171.00 FL	*171.00 FL
3	1		*FRONT BONNET INNER RUBBER	Serviceable	150.50 FL	*- FL
4	1		*FRONT BONNET INNER LOCK	Distorted	395.20 FL	*166.50 FL
5	1		*FRONT BONNET INNER LOCK BRACKET	Distorted	78.50 FL	*78.50 FL
6	2		*FRONT HEADLAMP	Mtg Cracked	5,161.00 FL	*5,161.00 FL
7	2		*FRONT HEADLAMP CHROME	Dented	371.00 FL	*371.00 FL
8	2		*FRONT HEADLAMP TOP BRACKET	Serviceable	90.00 FL	*- FL
9	2		*FRONT HEADLAMP LOWER BRACKET	Cracked	110.00 FL	*110.00 FL
10	1		*FRONT CENTRE GRILLE BASE	Cracked	550.20 FL	*381.80 FL
11	1		*FRONT CENTRE GRILLE OUTER GARNISH	Cracked	420.50 FL	*385.00 FL
12	1		*FRONT CENTRE GRILLE HONDA LOGO	Cracked	68.50 FL	*68.50 FL
13	1		*FRONT BUMPER	Bent	951.70 FL	*762.70 FL
14	10		*FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
15	2		*FRONT BUMPER SIDE RETAINER	Distorted	131.20 FL	*131.20 FL
16	1		*FRONT BUMPER LOWER LID	Serviceable	450.30 FL	*- FL
17	1		*FRONT BUMPER LOWER GRILLE	Serviceable	280.50 FL	*- FL
18	1		*FRONT BUMPER REINFORCEMENT	Bent	368.80 FL	*321.70 FL
19	2		*FRONT FENDER	Repair	1,361.00 FL	*- FL
20	2		*FRONT FENDER PROTECTOR	Serviceable	571.00 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Bent	681.20 FL	*576.20 FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	385.20 FL	*188.20 FL
23	1		*FRONT AIR-CON CONDENSOR	Serviceable	950.20 FL	*- FL
24	1		*FRONT RADIATOR	Serviceable	1,150.20 FL	*- FL
25	1		*SET FRONT BUMPER PLATE & CASING	Dented	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,072.70	9,860.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,204.54	1,963.08
Total Parts (\$\$)	12,868.16	7,897.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	100.00	20.00
2	TUFFKOTE	New	120.00	30.00
3	SPRAY PAINTING	New	1,000.00	800.00
4	LABOUR CHARGES	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,220.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >