



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23001998/Kny3e2 Date: 19/06/2023 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SBS 6488M	Veh. Inspected	SMH 7122P
Policy No.	D-22099843MFBP	Coverage (\$)	0.00
Claim No.	D23000629MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	22/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA HRV (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMRU1810GX201291	Colour	METALLIC DARK GREY
Odometer	77947 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	4 mm
L/H Front Tyre	215/60 R16	DUNLOP	4 mm
R/H Rear Tyre	215/60 R16	DUNLOP	3 mm
L/H Rear Tyre	215/60 R16	DUNLOP	3 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/02/2023	Inspection Date	07/03/2023
Survey held at	60 JALAN LAM HUAT #04-53 CARROS CENTRE S 737869		
Repairer	WIN AUTOMOTIVE SERVICES		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	