

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23002000/AYA3Q2**Date:** 27/06/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002597171		
Claimant Vehicle No :	SMD6346M	Insured Vehicle No :	SNG8583D		
Date of Loss:	18/02/2023	Nature of Claim:	TP	Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD6346M	Engine No:	2NRX346575
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Chassis No:	MHFZ28H3200055584
Reg. Date:	29/08/2018 (Man. Year: 2018)	Odometer:	67384 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,849.50	1,126.80	722.70	39.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	550.00	530.00	49.07
Paintwork Labour	800.00	400.00	400.00	50.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,729.50	2,076.80	1,652.70	44.31
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	3,729.50	1,650.00	2,079.50	55.76
+ GST 8.00/8.00% (S\$)	298.36	132.00	166.36	55.76
Nett Amount (S\$)	4,027.86	1,782.00	2,245.86	55.76
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,984.00		

INSPECTION

Date of Assignment:	22/02/2023	Present Location:	Success United Pte Ltd (HQ)
Date Inspected:	24/02/2023	Inspected At:	Success United Pte Ltd (HQ)
Estimated Period of Repair:	4.0 days		2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
			Singapore 417921

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD6346M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear tail gate (WCP)	Dented	480.00 F	*480.00 F
2	1		*Rear tail gate weatherstrip (WCP)	Not Necessary	150.00 F	*- F
3	1		*Rear tailgate mechanism lock (WCP)	Not Necessary	185.00 F	*- F
4	1		*Rear tailgate damper LH (WCP)	Not Necessary	130.00 F	*- F
5	1		*Rear Sienta emblem (WCP)	Necessary	38.00 F	*38.00 F
6	1		*Rear lower bumper (WCP)	Deformed	240.00 F	*240.00 F
7	1		*Rear bumper side holder LH (WCP)	Not Necessary	42.00 F	*- F
8	1		*Rear corner bumper LH (WCP)	Deformed	85.00 F	*85.00 F
9	1		*Rear bumper guard garnish LH (WCP)	Deformed	55.00 F	*55.00 F
10	3		*Rear windscreen moulding (WCP)	Necessary	90.00 F	*90.00 F
11	1		*Rear windscreen sealant	Necessary	40.00 FS	*40.00 FS
12	1		*Rear boot lamp LH (WCP)	Not Necessary	150.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,685.00	1,028.00
+ Margin on L,N Items 10.00/10.00% (S\$)	164.50	98.80
Total Parts (S\$)	1,849.50	1,126.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To putty and respray painting on boot lid, bumper and corner bumper LH.	New	800.00	400.00
<u>Labour Items</u>				
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & whereconsistent to the accident.	New	800.00	400.00
3	To remove, rearrange electrical wirings, check lighting.	New	80.00	30.00
4	Labour to remove, replace rear windscreen.	New	200.00	120.00
Gross Labour Cost (\$\$)			1,880.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >