

ASS. REC. BY:

REF:

TH / 23002008/KP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8122k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW 6341BYr Regn: 11, 20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pmtc.c. 1798Colour: M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 25388

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU203092791Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Blm or

Tyre Size: F: Sailun 195/65R15R: Maxis

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 6 mmL/Bal. 9 mmL/Bal. 6 mmD.O.A. 20/2/23D.O.I. 22/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/3 11pm 817001 Cuh

Data/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Data/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Date: 22/02/2023

Vehicle No: SMW6341B

Model: TOYOTA PRIUS 5DR HATCHBACK

Chassis: JTDKB3FU203092791 - 2020

Reg.Year: 2020

Not wither
11 Rmp 81700h
Recovery After Pain
4 days

Third Party Insurer: INDIA

Third Party Veh No: SHD2663H

Date of Accident: 20/02/2023

Estimator: VICTOR

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>R</i> \$220.00
2	REAR BUMPER LOWER GARNISH	1		<i>R</i> \$180.00
3	REAR BUMPER REINFORCEMENT	1		<i>R</i> \$115.00
4	REAR BUMPER REFLECTOR RH	1		<i>CM</i> \$25.00
5	REAR BUMPER SIDE BRACKET RH	1		<i>DI</i> \$60.00
6	REAR BUMPER ANTENNA SENSOR	1		<i>Sm</i> \$55.00
7	REAR END PANEL	1		<i>R</i> \$230.00
8	REAR END PANEL UPPER COVER	1		<i>R</i> \$80.00
9	REAR BUMPER TOWING COVER	1		<i>na</i> \$20.00
10	REAR TAILGATE	1		<i>R</i> \$540.00
11	REAR TAILGATE "PRIUS" EMBLEM	1		<i>na</i> \$30.00
12	REAR TAILGATE "HYBRID" EMBLEM	1		<i>na</i> \$30.00
13	REAR TAILGATE WEATHERSTRIP	1		<i>Sm</i> \$140.00
14	REAR WINDSCREEN MOULDING	1		<i>na</i> \$30.00
15	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$1,755.00
COST +10%				\$175.50
PARTS TOTAL				\$1,930.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>na</i> \$50.00
2	REAR BUMPER REVERSE SENSOR	1		<i>na</i> \$300.00
3	REAR WINDSCREEN SEALANT	1		<i>na</i> \$80.00
4	REAR END PANEL JOINT SEALANT	1		<i>na</i> \$80.00
5	REAR END PANEL UPPER COVER CLIPS	1		<i>na</i> \$30.00
S/N TOTAL				\$540.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS.

\$700.00 *500*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.

\$700.00 *600*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

na \$150.00 *X*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 22/02/2023
Vehicle No: SMW6341B
Model: TOYOTA PRIUS 5DR HATCHBACK
Chassis: JTDKB3FU203092791 - 2020
Reg. Year: 2020

Third Party Insurer: INDIA
Third Party Veh No: SHD2663H
Date of Accident: 20/02/2023
Estimator: VICTOR
Surveyor:

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

nn \$120.00 X

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 50/

TO TUFF KOTE & UNDERSEAL MATERIALS.

nn \$100.00 X

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$120.00 X

LABOUR TOTAL \$2,010.00

TOTAL \$4,480.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

