4/4/23, 10:40 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III23002024/UWY3E2

04/04/2023 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447 02

**Claimant Vehicle** SLJ4204H Insured Vehicle No: SLV1582Y

No:

17/02/2023 Nature of Claim: ΤP Claim No: MFL2023D0002072 Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLJ4204H** Reg No:

Make & Model: TOYOTA HARRIER, 2.0 Premium (A) **Engine No:** 3ZRB824771 Reg. Date: 09/12/2016 (Man. Year: 2016) Chassis No: ZSU600083204 Odometer: 75419 km

Colour: White

1986 cc **Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 235/55 R18 235/55 R18 Rear Tyre Size: Rear Left Side: Front Left Side: APLUS 7 mm Bridgestone 7 mm Front Right Side: APLUS 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	0.00	0.00	0.00	
	Approved Total (Overridden) (S\$)		2,000.00		
	Nett Amount (S\$)	0.00	2,000.00	-2,000.00	

**INSPECTION** 

23/02/2023 Date of Assignment:

Kaizen Motors Pte Ltd (HQ)

68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT 23/02/2023 Inspected At: Date Inspected:

Singapore 417896

4.0 days Estimated Period of Repair:

MARCUS CHUA Adjuster: Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2023)

Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ4204H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

4/4/23, 10:40 AM Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >