

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI23002031/KWP3E2  
**Date:** 08/03/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU007872
<b>Claimant Vehicle No :</b>	SHF743M	<b>Insured Vehicle No :</b>	GBE342M
Date of Loss:	18/02/2023	Nature of Claim:	TP
		Claim No:	M2301150

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHF743M</b>		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003034
Reg. Date:	30/06/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282731
Colour:	White	Odometer:	937014 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,547.35	2,253.45	1,293.90	36.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,560.00	890.00	5,670.00	86.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,107.35</b>	<b>3,143.45</b>	<b>6,963.90</b>	<b>68.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>(S\$)</b>	10,107.35	2,500.00	7,607.35	75.27
<b>+ GST 8.00/8.00% (S\$)</b>	808.59	200.00	608.59	75.27
<b>Nett Amount (S\$)</b>	<b>10,915.94</b>	<b>2,700.00</b>	<b>8,215.94</b>	<b>75.27</b>

INSPECTION

Date of Assignment:	24/02/2023		
Date Inspected:	21/02/2023	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHF743M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled / Mtg Cracked	747.20 FL	*747.20 FL
2	1		*BUMPER RETAINER FRT LH	Cracked	101.40 FL	*101.40 FL
3	1		*HEADLAMP LH	Mtg Broken	743.60 FL	*743.60 FL
4	1		*HEADLAMP PANEL FRT LH	Repair	128.30 FL	*- FL
5	1		*BUMPER BRACKET FRT LH (HEADLAMP LOWER)	Cracked	116.47 FL	*116.47 FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
7	1		*FENDER PANEL FRT LH	Bent	437.10 FL	*437.10 FL
8	1		*WHEELARCH FRT LH	Torn	191.40 FL	*191.40 FL
9	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
10	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
11	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
12	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
13	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
14	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	65.00 FS	*- FS
15	1		*BUMPER CLIP FRT	Necessary	85.00 FS	*85.00 FS
16	1		*FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,914.28</b>	<b>2,487.17</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	366.93	233.72
<b>Total Parts (\$)</b>	<b>3,547.35</b>	<b>2,253.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,560.00</b>	<b>890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >