

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS23002032/ANY3Q2**Date:** 14/06/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

**Claimant Vehicle No :** SMP4652D **Insured Vehicle No :** SLD6293T

Date of Loss: 21/02/2023 Nature of Claim: TP Claim No: 2023 32005679FR

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMP4652D**

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: L15B6020277

Reg. Date: 26/09/2019 (Man. Year: 2019) Chassis No: GK82100218

Colour: White Odometer: 303623 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm

Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,657.04	4,744.80	5,912.24	55.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,080.00	2,000.00	49.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,737.04</b>	<b>6,824.80</b>	<b>7,912.24</b>	<b>53.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,737.04</b>	<b>5,400.00</b>	<b>9,337.04</b>	<b>63.36</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 23/02/2023

Date Inspected: 22/02/2023 Inspected At: JEC AUTO SERVICE PTE LTD (HQ)  
1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY  
Singapore 417883

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jun 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP4652D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE LAMP	Not Necessary	154.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	993.30 FL	*993.30 FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	60.80 FL	*- FL
4	1		*REAR BUMPER REFLECTOR	N/S Cracked	136.60 FL	*68.30 FL
5	2		*REAR BUMPER SIDE SPONGE	Cracked	120.40 FL	*120.40 FL
6	1		*REAR BUMPER TOP CHROME MOULDING	Cracked	109.40 FL	*109.40 FL
7	1		*REAR END PANEL	Dented	615.40 FL	*615.40 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	248.70 FL	*248.70 FL
9	2		*REAR END PANEL SIDE EXTENSION	Repair	300.80 FL	*- FL
10	1		*REAR END PANEL BUZZER	Not Necessary	80.90 FL	*- FL
11	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	108.90 FL	*- FL
12	2		*TAILLAMP	Cracked	1,041.60 FL	*1,041.60 FL
13	1		*TAILGATE	Dented	1,193.40 FL	*1,193.40 FL
14	1		*TAILGATE LOCK	Damaged	265.20 FL	*265.20 FL
15	1		*TAILGATE WEATHERSTRIPE	Cut	185.40 FL	*185.40 FL
16	1		*TAILGATE INNER TRIM BOARD	Cracked	398.40 FL	*398.40 FL
17	2		*TAILGATE DAMPER	Not Necessary	484.20 FL	*- FL
18	2		*TAILGATE REFLECTOR	Not Necessary	771.80 FL	*- FL
19	1		*TAILGATE OUTER GARNISH	Not Necessary	363.30 FL	*- FL
20	1		*TAILGATE GLASS MOULDING	Necessary	140.90 FL	*140.90 FL
21	1		*HONDA LOGO	Not Necessary	45.90 FL	*- FL
22	1		*SHUTTLE WORDING	Necessary	50.60 FL	*50.60 FL
23	2		*REAR FENDER INNER TRIM	Not Necessary	674.80 FL	*- FL
24	1		*SPARE TYRE PANEL	Repair	1,185.90 FL	*- FL
25	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	528.20 FL	*- FL
26	1		*TOOLS TRAY	Not Necessary	321.90 FL	*- FL
27	1		*TOOLS TRAY JACK COVER	Not Necessary	100.90 FL	*- FL
28	1		*UTILITY TRAY SPONGE	Not Necessary	298.40 FL	*- FL
29	1		*REAR EXHAUST PIPE	Not Necessary	688.20 FL	*- FL
30	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.90 FL	*- FL
31	1		*REAR EXHAUST PIPE GASKET	Not Necessary	34.10 FL	*- FL
32	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	145.60 FL	*- FL
33	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
34	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
37	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
39	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
41	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
42	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
43	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,033.80	5,831.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,376.76	1,086.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>10,657.04</b>
						<b>4,744.80</b>
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,500.00	800.00
2	SPRAY PAINTING	New	1,400.00	800.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
10	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
11	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,080.00</b>	<b>2,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >