

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile					
	SERVE YOU MOT	OR SERVICE	Ref:	CS/TP23002039/Knp3m4	
	BLOCK 5033 ANG #01-265	MO KIO INDUSTRIAL PARK 2	Date:	24/02/2023	
	SINGAPORE 569536				
			Code:	TP392	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	PC 7901Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	23/02/2023	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE (A)	c.c	2754	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	GDH2232000860	Colour	SILVER	
	Odometer	282532 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15X8	DURATURN	7 mm	
	L/H Front Tyre	195 R15X8	DURATURN	7 mm	
	R/H Rear Tyre	195 R15X8	DURATURN	8 mm	
	L/H Rear Tyre	195 R15X8	DURATURN	8 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR WINDSCREEN SHATTERED.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	15/02/2023	Inspection Date	17/02/2023	
	Survey held at SERVE YOU MOTOR SERVICE				
	BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				
	•				