

Kenneth

ASS. REC. BY:

REF: TP1

CS/TP23002039/Knp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

See You

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

17.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC 78017

Yr Regn:

05 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

c.c

2758

Colour:

Pink

A/C:

Insured / Std / NI / NA

Sp. Reading

282532

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GDH 2232000860

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

195R15X8

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Danlun

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

15/2/23

D.O.I.

17/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear wheel shorter

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1489.73 to submit report to workshop ASAP
(red, \$552.14, 27%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

24/02/23

Date/Time, File Return to?

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Transportation

\$ - RS. SI

Report Format :

ump Sum / I.B.I: (\$ 1489.73

SERVE YOU MOTOR PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

Name : Ret Tours Pte Ltd

Registration no. : PC 7901 Z Toyota Hiace Commuter 2.8 GL AT

Date : 15-Feb-23 Quotation No. : 79010215

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

- | | | |
|---|---|--------------------------------|
| 1 | 1 | Rear windscreen glass |
| 2 | 1 | Windscreen glass sealant |
| 3 | 1 | Rear windscreen glass moulding |

Shortland
 \$ 1,466.30 ✓
nn \$ 120.00 *80sn*
nn \$ 138.00 x
 25% \$ 1,724.30
 10% \$ 172.43
 \$ 1,551.87

SPECIAL NETT ITEMS

- | | | |
|---|---|-----------------------|
| 1 | 1 | Company logo sticker |
| 2 | 1 | Advertisement Sticker |

nn \$ 80.00 ✓
nn \$ 150.00 *100%*
 \$ 230.00

Labour Charge

- | | |
|---|---|
| 1 | To dismantle and refit rear windscreen glass |
| 2 | To remove and refit rear wiper motor for facility repair. Check wiring. |

\$ 180.00 *120%*
 \$ 80.00 *50%*
 \$ 260.00

Total Parts and Labour Cost of Repair

\$ 2,041.87

Not Authorized
Pruning After Repair
1 day
 \$ 1489.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: