



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS/HSB23002041/Uqp3m4 Date: 10/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 8468R	Veh. Inspected	GBK 5876A	
Policy No.	GA530408	Coverage (\$)	0.00	
Claim No.	S3M04JOV	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	23/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX 2.8 (A)	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GDH2011037124	Colour	SILVER	
Odometer	94867 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/02/2023	Inspection Date	27/02/2023	
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	