

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002046/SVP3Q2**Date:** 13/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00130752200
Claimant Vehicle No :	SMU5708U	Insured Vehicle No :	SLV215P
Date of Loss:	08/01/2023	Nature of Claim: TP	Claim No: SNM23D200214/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU5708U	Engine No:	L15B5672646
Make & Model:	HONDA HR-V, 1.5 LX CVT (A)	Chassis No:	JHMRU1830JX202638
Reg. Date:	19/08/2020 (Man. Year: 2020)	Odometer:	28648 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,192.00	2,868.64	13,323.36	82.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	860.00	4,240.00	83.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,292.00	3,728.64	17,563.36	82.49
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	21,292.00	3,000.00	18,292.00	85.91
+ GST 8.00/8.00% (S\$)	1,703.36	240.00	1,463.36	85.91
Nett Amount (S\$)	22,995.36	3,240.00	19,755.36	85.91

INSPECTION

Date of Assignment:	22/02/2023	
Date Inspected:	23/02/2023 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2023)
Parts:	M1-SUV	HONDA HR-V 1.5 LX CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU5708U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	975.50 FL	*524.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	30.20 FL	*30.20 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	30.20 FL	*- FL
4	1		*FRONT BUMPER BRACKET RH	Not Necessary	32.50 FL	*- FL
5	1		*FRONT BUMPER BRACKET LH	Not Necessary	32.50 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	392.70 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	50.00 FL	*- FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	29.80 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	386.00 FL	*- FL
10	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	108.30 FL	*- FL
11	1		*FRONT BUMPER LOWER SPOILER	Cracked	419.10 FL	*387.00 FL
12	1		*FRONT BUMPER LOWER RUBBER	Not Necessary	115.40 FL	*- FL
13	1		*FRONT GRILLE BASE	Not Necessary	418.00 FL	*- FL
14	1		*FRONT GRILLE OUTER CHROME	Not Necessary	260.70 FL	*- FL
15	1		*FRONT GRILLE EMBLEM	Not Necessary	36.70 FL	*- FL
16	1		*FRONT GRILLE UPPER CENTRE BRACKET	Not Necessary	50.10 FL	*- FL
17	1		*FRONT HEADLAMP ASSEMBLY RH	Cracked	1,980.00 FL	*1,859.00 FL
18	1		*FRONT HEADLAMP ASSEMBLY LH	Not Necessary	1,980.00 FL	*- FL
19	1		*FRONT HEADLAMP LOWER BRACKET RH	Broken	41.80 FL	*41.80 FL
20	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	41.80 FL	*- FL
21	1		*FRONT BONNET	Not Necessary	981.50 FL	*- FL
22	1		*FRONT BONNET LOCK	Not Necessary	119.30 FL	*- FL
23	1		*FRONT BONNET INSULATOR	Not Necessary	167.50 FL	*- FL
24	1		*FRONT BONNET HINGE RH	Not Necessary	53.40 FL	*- FL
25	1		*FRONT BONNET HINGE LH	Not Necessary	53.40 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Not Necessary	649.20 FL	*- FL
27	1		*AIRCON CONDENSER	Not Necessary	657.90 FL	*- FL
28	1		*RADIATOR	Not Necessary	1,623.60 FL	*- FL
29	1		*FRONT FENDER RH	Repair	471.60 FL	*- FL
30	1		*FRONT FENDER INNER COWLING RH	Not Necessary	170.50 FL	*- FL
31	1		*FRONT FENDER WHEEL ARCH GARNISH RH	Cracked	206.30 FL	*206.30 FL
32	1		*FRONT WHEEL RIM RH	Cut	836.20 FL	*500.00 FL
33	1		*FRONT WHEEL HUB RH	Not Necessary	211.30 FL	*- FL
34	1		*FRONT WHEEL HUB BEARING RH	Not Necessary	155.90 FL	*- FL
35	1		*FRONT SHOCK ABSORBER RH	Not Necessary	387.60 FL	*- FL
36	1		*FRONT LOWER ARM RH	Not Necessary	444.80 FL	*- FL
37	1		*FRONT STABILIZER LINK	Not Necessary	53.40 FL	*- FL
38	1		*FRONT KNUCKLE ARM RH	Not Necessary	280.70 FL	*- FL
39	1		*TIE ROD END RH	Not Necessary	82.70 FL	*- FL
40	1		*FRONT DOOR SIDE MIRROR ASSEMBLY RH	Not Necessary	667.20 FL	*- FL
41	1		*FRONT DOOR SIDE MIRROR COVER RH	Not Necessary	71.20 FL	*- FL
42	1		*FRONT DOOR RH	Not Necessary	903.20 FL	*- FL
43	1		*FRONT DOOR UPPER HINGE RH	Not Necessary	38.50 FL	*- FL
44	1		*FRONT DOOR LOWER HINGE RH	Not Necessary	40.90 FL	*- FL
45	1		*FRONT DOOR OUTER GLASS MOULDING RH	Not Necessary	55.60 FL	*- FL
46	1		*FRONT DOOR LOCK RH	Not Necessary	225.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT DOOR WEATHERSTRIP RH (TOP)	Not Necessary	85.00 FL	*- FL
48	1		*FRONT DOOR WEATHERSTRIP RH (LOWER)	Not Necessary	25.00 FL	*- FL
49	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	88.00 FL	*- FL
50	1		*FRONT DOOR GLASS REGULATOR WITH MOTOR RH	Not Necessary	382.00 FL	*- FL
51	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	650.00 FL	*- FL
52	1		*ROCKER PANEL GARNISH RH	Not Necessary	415.30 FL	*- FL
53	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
54	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
55	1		*SET FRONT BUMPER GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
56	1		*SET FRONT BUMPER FOG LAMP GARNISH RH CLIPS	Not Necessary	30.00 FS	*- FS
57	1		*SET FRONT GRILLE BASE CLIPS	Not Necessary	50.00 FS	*- FS
58	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*SET FRONT FENDER INNER COLWING RH CLIPS	Not Necessary	40.00 FS	*- FS
60	1		*SET FRONT DOOR INNER TRIM BOARD RH CLIPS	Not Necessary	50.00 FS	*- FS
61	1		*SET ROCKER PANEL GARNISH RH CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*FRONT BONNET SEALANT	Not Necessary	150.00 FS	*- FS
63	1		*FRONT FENDER RH SEALANT	Not Necessary	150.00 FS	*- FS
64	1		*FRONT DOOR RH SEALANT	Not Necessary	150.00 FS	*- FS
65	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
66	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,925.00	3,578.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,733.00	709.66
Total Parts (\$\$)	16,192.00	2,868.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,600.00	400.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	400.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO TRANSFER FRONT DOOR RH MECHANISM	New	150.00	0.00
5	TO REMOVE & REFIX AIRCON CONDENSER AND TOP UP GAS	New	150.00	0.00
6	TO REMOVE & REFIX RADIATOR AND PRESSURE TEST	New	150.00	0.00
7	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	30.00
8	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	0.00
9	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	350.00	0.00
10	TO REMOVE & REFIX FRONT TYRE AND CONDUCT WHEEL BALANCING	New	150.00	0.00
11	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
12	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (\$\$)			5,100.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >