

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI23002048/UNP3Q2**Date:** 05/04/2023**REFERENCE**

Insured/Claimant: JUSTINA ZHUO MIAO EN Policy No: DMPCSNA00155932202

Date of Loss: 18/02/2023

Nature of Claim: OD

Claim No: SNM23D201329/C01/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK8251C**

Make & Model: AUDI A6, 2.0 (A)

Engine No: CDN403210

Reg. Date: 16/07/2014 (Man. Year: 2014)

Chassis No: WAUZZZ4G6EN111149

Colour: Black

Odometer: 163434 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$45,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 245/40 R19

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,457.00	26,925.00	532.00	1.94
Miscellaneous Items	600.00	395.00	205.00	34.17
Labour	1,286.69	1,303.00	-16.31	-1.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,343.69	28,623.00	720.69	2.46
Approved Total (Overridden) (S\$)		13,000.00		
(S\$)	29,343.69	13,000.00	16,343.69	55.70
+ GST 8.00/8.00% (S\$)	2,347.50	1,040.00	1,307.50	55.70
Nett Amount (S\$)	31,691.19	14,040.00	17,651.19	55.70

INSPECTION

Date of Assignment: 22/02/2023 Present Location:

SME Motor Pte Ltd (Kaki Bukit)

Date Inspected: 24/02/2023 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2023)
Parts:	143	AUDI A6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK8251C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		27,457.00 F	*26,925.00 F
F=Franchise part.						
				Total Parts (S\$)	27,457.00	26,925.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	600.00	395.00
Sub Total (\$\$)			600.00	395.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	651.00	680.40
2	SPRAY PAINTING	New	635.69	622.60
Gross Labour Cost (\$\$)			1,286.69	1,303.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >