

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002051/RNP3Q2**Date:** 06/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00138542202

Claimant Vehicle No : FBT3612K **Insured Vehicle No :** YP8690A

Date of Loss: 01/02/2023 Nature of Claim: TP Claim No: SNM23D200865/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBT3612K**

Make & Model: DUCATI SCRAMBLER SIXTY2, 399cc Engine No: DPT800A2H914490

Reg. Date: 25/01/2022 (Man. Year: 2021) Chassis No: ML05K00AAMT000169

Colour: Multi-colour Odometer: 5248 km

Engine Capacity: 803 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R19 Rear Tyre Size: 120/60 R17

Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,403.04	3,999.20	1,403.84	25.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	1,000.00	3,120.00	75.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,523.04	4,999.20	4,523.84	47.50
+ GST 8.00/8.00% (S\$)	761.84	399.94	361.90	47.50
Nett Amount (S\$)	10,284.88	5,399.14	4,885.74	47.50

INSPECTION

Date of Assignment: 23/02/2023

Date Inspected: 23/02/2023 Inspected At: 45 LENG KEE ROAD
SINGAPORE 159103
Repairer: Wearnes Automotive Pte Ltd (Leng Kee)

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Jun 2023)	
Parts:	N/A	DUCATI SCRAMBLER SIXTY2 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBT3612K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE	Necessary	45.00 FS	*45.00 FS
2	1		*SIDE STAND	Scratched	260.80 FS	*260.80 FS
3	1		*COMPLETE SPRING	Not Necessary	26.40 FS	*- FS
4	1		*INNER SPRING	Not Necessary	7.60 FS	*- FS
5	1		*LINK SIDE STAN	Not Necessary	7.84 FS	*- FS
6	1		*NUT	Not Necessary	2.40 FS	*- FS
7	1		*AXLE SIDE STAN	Not Necessary	10.00 FS	*- FS
8	1		*SCREW	Not Necessary	2.16 FS	*- FS
9	1		*SWITCH STAND	Not Necessary	1,001.28 FS	*- FS
10	1		*SCREW TBEIF M10	Not Necessary	7.68 FS	*- FS
11	1		*BRACKET SIDE S	Not Necessary	132.48 FS	*- FS
12	1		*SPACER	Not Necessary	2.48 FS	*- FS
13	1		*SCREW	Not Necessary	7.28 FS	*- FS
14	1		*SCREW	Not Necessary	2.88 FS	*- FS
15	1		*LOWER CHAIN SLI	Not Necessary	14.40 FS	*- FS
16	1		*STAY COMP	Bent	449.00 FS	*449.00 FS
17	1		*NUT SPRING M5	Necessary	4.10 FS	*4.10 FS
18	1		*SPACER	Necessary	2.80 FS	*2.80 FS
19	1		*SCREW SPECIAL	Necessary	1.20 FS	*1.20 FS
20	1		*CUSHION SEAT	Scratched	2.50 FS	*2.50 FS
21	1		*SCREW	Necessary	4.40 FS	*4.40 FS
22	1		*COVER	Cracked	16.80 FS	*16.80 FS
23	1		*REFLEX REFLECTOR	Scratched	6.90 FS	*6.90 FS
24	1		*NUT ,SPRING	Necessary	0.30 FS	*0.30 FS
25	1		*WASHER 4.5X9X0	Necessary	1.50 FS	*1.50 FS
26	1		*PLATE HOLDER	Not Necessary	23.52 FS	*- FS
27	1		*LAMP ,LICENSE P	Scratched	76.90 FS	*76.90 FS
28	1		*VIBRATION DAMPE	Necessary	108.40 FS	*108.40 FS
29	1		*SCREW	Not Necessary	1.04 FS	*- FS
30	1		*SCREW	Not Necessary	1.12 FS	*- FS
31	1		*TOOTHED LOCK WA	Necessary	1.20 FS	*1.20 FS
32	1		*SCREW TCEIF M8X	Necessary	4.50 FS	*4.50 FS
33	1		*SCREW TCEIF M6X	Necessary	2.90 FS	*2.90 FS
34	1		*WASHER	Necessary	0.80 FS	*0.80 FS
35	1		*CLAMP	Necessary	0.50 FS	*0.50 FS
36	1		*PLUG	Necessary	12.50 FS	*12.50 FS
37	1		*REAR -VIEW MIRRO	Scratched	166.50 FS	*166.50 FS
38	1		*LEFT COVER	Scratched	14.40 FS	*14.40 FS
39	1		*SPACER	Necessary	43.50 FS	*43.50 FS
40	1		*VALVE ,BREATH	Necessary	2.10 FS	*2.10 FS
41	1		*PISTON ASSEMBLY	Necessary	260.80 FS	*260.80 FS
42	1		*DUST COVER	Scratched	32.50 FS	*32.50 FS
43	1		*CLUTCH MASTER C	Not Working	535.70 FS	*535.70 FS
44	1		*BRACKET ,CLUTCH	Necessary	28.10 FS	*28.10 FS
45	1		*CLUTCH CONTROL	Not Working	117.60 FS	*117.60 FS
46	1		*GASKET	Necessary	3.80 FS	*3.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*MICROSWITCH	Not Working	154.70 FS	*154.70 FS
48	1		*BOLT BRAKE HOS	Necessary	20.20 FS	*20.20 FS
49	1		*WASHER 10X14X1	Necessary	0.50 FS	*0.50 FS
50	1		*SCREW TCEIR M6X	Necessary	0.50 FS	*0.50 FS
51	1		*BOLT ,PIVOT	Necessary	13.80 FS	*13.80 FS
52	1		*CLUTCH LEVER	Broken	216.60 FS	*216.60 FS
53	1		*PLUG ASSY	Necessary	92.60 FS	*92.60 FS
54	1		*SCREW ,SPECIAL	Necessary	22.60 FS	*22.60 FS
55	1		*SCREW	Necessary	1.00 FS	*1.00 FS
56	1		*SPACER	Necessary	18.90 FS	*18.90 FS
57	1		*RUBBER PAD	Necessary	2.50 FS	*2.50 FS
58	1		*FRONT MUDGUARD	Scratched	295.90 FS	*295.90 FS
59	1		*BRACE ,FRONT FE	Bent	55.40 FS	*55.40 FS
60	1		*RUBBER PAD	Necessary	6.00 FS	*6.00 FS
61	1		*SCREW	Necessary	7.40 FS	*7.40 FS
62	1		*RIGHT COVER	Not Necessary	27.60 FS	*- FS
63	1		*PROTECTION LEF	Necessary	36.30 FS	*36.30 FS
64	1		*SCREW ,SPECIAL	Necessary	1.20 FS	*1.20 FS
65	1		*BRACKET ,BRAKE	Necessary	52.80 FS	*52.80 FS
66	1		*FRONT L.H.PLAT	Bent	129.40 FS	*129.40 FS
67	1		*SCREW	Necessary	4.80 FS	*4.80 FS
68	1		*SCREW TCEIF M6X	Necessary	3.00 FS	*3.00 FS
69	1		*GEAR CONTROL LE	Not Necessary	39.76 FS	*- FS
70	1		*SCREW TCEIF M6X	Necessary	2.50 FS	*2.50 FS
71	1		*ROD ,GEAR SHIFT	Not Working	73.20 FS	*73.20 FS
72	1		*PIN PEDAL	Necessary	10.20 FS	*10.20 FS
73	1		*GEARCHANGE LEVE	Bent	102.60 FS	*102.60 FS
74	1		*RUBBER PAD	Necessary	3.40 FS	*3.40 FS
75	1		*PLUG	Necessary	3.80 FS	*3.80 FS
76	1		*O-RING	Necessary	0.40 FS	*0.40 FS
77	1		*WASHER	Necessary	1.30 FS	*1.30 FS
78	1		*CIRCLIP E-TYPE	Necessary	1.00 FS	*1.00 FS
79	1		*FOOTREST PIN	Necessary	9.90 FS	*9.90 FS
80	1		*SPRING FOOTRES	Necessary	3.30 FS	*3.30 FS
81	1		*LEFT FOOTREST	Scratched	45.20 FS	*45.20 FS
82	1		*FOOT PEG RUBBER	Necessary	13.40 FS	*13.40 FS
83	1		*LEFT FOOTREST	Scratched	124.70 FS	*124.70 FS
84	1		*REAR L.H.PLATE	Bent	101.40 FS	*101.40 FS
85	1		*SPRING RETAINER	Necessary	7.10 FS	*7.10 FS
86	1		*SPRING	Necessary	1.60 FS	*1.60 FS
87	1		*BALL	Necessary	0.60 FS	*0.60 FS
88	1		*HEEL GUARD L.H	Scratched	40.60 FS	*40.60 FS
89	1		*SCREW	Necessary	1.10 FS	*1.10 FS
90	1		*NUT ,SELF-LOCK I	Necessary	0.40 FS	*0.40 FS
91	1		*FLASHER LIGHT	Scratched	107.40 FS	*107.40 FS
92	1		*FLASHER LIGHT	Not Necessary	85.92 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$)**5,403.04****3,999.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT DAMAGE ASSESSMENT	New	70.00	0.00
2	TO REPLACE DAMAGED PARTS CAUS	New	4,050.00	1,000.00
Gross Labour Cost (S\$)			4,120.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >