

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23002052/KWP3Q2**Date:** 08/03/2023**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00019682200

**Claimant Vehicle  
No :** SKS4033Z**Insured  
Vehicle No :** SNH2928C

Date of Loss: 19/12/2022

Nature of Claim: TP

Claim  
No: SNM22D209223/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKS4033Z**

Make &amp; Model: HONDA CIVIC, 1.6 5AT (A)

Engine No: R16A14003493

Reg. Date: 24/09/2009 (Man. Year: 2008)

Chassis No: JHMFD46209S200928

Colour: Metallic Grey

Odometer: 402149 km

Engine Capacity: 1595 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Airvo 8 mm

Rear Left Side: Airvo 8 mm

Front Right Side: Airvo 8 mm

Rear Right Side: Airvo 8 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 550.40            | 0.00              | 550.40            | 100.00        |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 1,550.00          | 750.00            | 800.00            | 51.61         |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>2,100.40</b>   | <b>750.00</b>     | <b>1,350.40</b>   | <b>64.29</b>  |

**INSPECTION**

Date of Assignment: 23/02/2023

Date Inspected: 24/02/2023 Inspected At:

Ngs Motorsport Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Ind Pk 2A, #05-18 AMK  
AutoPoint  
Singapore 568047

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |  |   |
|---------------|--|---|
| Reference     |  |   |
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 08 Mar 2023)             |
| Parts:        | 143  | HONDA CIVIC 1.6 5AT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                         |
| Print Code:   | (Unsubmitted, no print-code for SKS4033Z)  |   |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

Recommended Parts

| No. | Qty | Part No. | Particulars             | Condition   | Repairer's  | Amount                            |
|-----|-----|----------|-------------------------|-------------|---|-----------------------------------|
| 1   | 1   |          | *FRT DOOR ASSY RH (NPA) | Repair      | 0.00 FL   | *- FL                             |
| 2   | 1   |          | *RR DOOR ASSY RH (NPA)  | Repair      | 0.00 FL   | *- FL                             |
| 3   | 1   |          | *SIDE MIRROR RH         | Serviceable | 688.00 FL   | *- FL                             |
|     |     |          |                         |             |   | F=Franchise part. L=ListItemDisc. |
|     |     |          |                         |             | Sub Total (\$\$)                                    | 688.00 0.00                       |
|     |     |          |                         |             | - List Item Discount on L Items 20.00/20.00% (\$\$) | 137.60 0.00                       |
|     |     |          |                         |             | Total Parts (\$\$)                                  | 550.40 0.00                       |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount        |
|--------------------------------|--|----------|-----------------|---------------|
| <b>Labour Items</b>            |  |          |                 |               |
| 1                              | TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENTS /ATTACHMENTS,STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL INACCORDENCE WITH FACTORY SPECIFICATIONS ,REPLACE /REPOSITION DAMAGED PARTS ,REFIT ALIGN INTO POSITION .REFIX ALL NECESSARY COMPONENTS /ATTACHMENTS | New      | 700.00          | 150.00        |
| 2                              | SPRAY PAINT ON REPLACE /REPAIR BODY PARTS  | New      | 800.00          | 600.00        |
| 3                              | TO REMOVE/REFIT WIRE HARNESS ,ALL RELATED CONNECTOR ,CHECK PROPER FUNCTION   | New      | 50.00           | 0.00          |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>1,550.00</b> | <b>750.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >