

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1718G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,171.40	-
1	ROCKER COVER GARNISH RH	SCRATCHED	732.80	732.80
1	REAR DOOR RH	BUCKLED	2,416.80	2,416.80
1	REAR DOOR REGULATOR RH	NOT NECESSARY	660.90	-
1	REAR DOOR POWER MOTOR RH	NOT NECESSARY	158.60	-
1	FRT DOOR RH	TO REPAIR SEE LABOUR	2,707.70	-
	LESS 20% DISCOUNT		-1,769.64	-629.92
			7,078.56	2,519.68
	<u>SPECIAL NETT ITEMS</u>			
1	FRT DOOR COMFORT LOGO STICKER RH (SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER RH (SN)	NECESSARY	80.00	80.00
			155.00	155.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND FRT DOOR RH.		900.00	840.00
	SPRAY PAINTING CHARGE.		1,100.00	750.00
	TRANSFER OF DOOR.		240.00	80.00
	TUFF KOTE.		60.00	20.00
			2,300.00	1,690.00
	GRAND TOTAL		9,533.56	4,364.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,500.00

Report Ref No. NS/INC23002058/Svp3m4


S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor


K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.