4/25/23, 11:23 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd. Our File No: CS/AIS23002060/RQY3Q2

79 Robinson Road #09-01 Date: 25/04/2023 Singapore 068897

**REFERENCE** 

Insured/Claimant: SANTOSH NARAYANLAL RADHALAL PATEL Policy No: SP2003008571

Date of Loss: 14/02/2023 Nature of Claim: OD Claim No: 202332005476

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SMQ6407C** 

Make & Model: BMW 216I, 1.5 (A) 32865757B38A15A Engine No: 27/11/2019 (Man. Year: 2019) Chassis No: WBA2X920X07E56911 Reg. Date:

Colour: Blue Odometer: 30656 km

**Engine Capacity:** 1499 cc

Market Value/New Car

S\$112,000.00 Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes **Engine Modification:** Nο Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,595.70	1,365.35	1,230.35	47.40
Miscellaneous Items		0.00	0.00	0.00	
Labour		10,054.00	6,292.00	3,762.00	37.42
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,649.70	7,657.35	4,992.35	39.47
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	12,049.70	7,057.35	4,992.35	41.43
	+ GST 8.00/8.00% (S\$)	963.98	564.59	399.39	41.43
	Nett Amount (S\$)	13,013.68	7,621.94	5,391.74	41.43

**INSPECTION** 

Date of Assignment: 23/02/2023

Performance Motors Limtied (HQ) Date Inspected: 13/03/2023 Inspected At: 303 Alexandra Road, Singapore

Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/25/23, 11:23 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Apr 2023)

Parts: M1-MPV BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ6407C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1	*FRT LH DOOR	Repair	1,050.40 FS	*-FS
3	1	*RR LH DOOR	Bent	1,285.35 FS	*1,285.35 FS
4	1	*RH SEALING COLUMN B BOTTOM	Not Necessary	59.65 FS	*-FS
5	1	*LH SEAL A PILLAR	Not Necessary	50.30 FS	*- FS
F=Fra	anchise part. S=Spc	Nett.	_		
			Total Parts (S\$)	2,595.70	1,365.35
			_		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REPLACE RH BOTH DOORS AND MAKE GOOD OF REAR BUMPER AND REAR LEFT FENDER	New	4,250.00	2,550.00
2	TO PAINTING LH BOTH DOORS , REAR LEFT FENDER AND REAR BUMPER	New	4,152.00	2,958.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (2 DOORS)	New	1,062.00	504.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	236.00	112.00
	Gross Labour Cost (S\$)		10,054.00	6,292.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >