

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 644Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED / DENTED	500.00	500.00
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	300.00	-
1	FRONT GRILLE	SERVICEABLE	350.00	-
1	FRONT GRILLE EMBLEM	SERVICEABLE	100.00	-
1	FRONT REINFORCEMENT	TO REPAIR SEE LABOUR	350.00	-
1	HEADLAMP LHS	CUT	1,250.00	1,250.00
1	FRONT REINFORCEMENT SPONGE (ADDITIONAL)	CRACKED	100.00	100.00
	LESS 25% DISCOUNT		-737.50	-462.50
			2,212.50	1,387.50
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
			60.00	60.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT REINFORCEMENT.		1,000.00	200.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,000.00	220.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		100.00	20.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
			2,200.00	440.00
	GRAND TOTAL		4,472.50	1,887.50

Report Ref No. CS/SPF23002061/Kwy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,500.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/SPF23002061/Kwy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$1,800

KONG SENG CHEONG

Licensed Appraiser