

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4948S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,062.00	945.00
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	REAR BUMPER SIDE RETAINER (RHS)	NECESSARY	85.00	65.00
1	REAR TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR TAILGATE "MAZDA" BADGE	NECESSARY	70.00	42.00
1	REAR TAILGATE "5" BADGE	NECESSARY	45.00	38.00
1	REAR TAILGATE "SKYACTIVE" BADGE	NECESSARY	80.00	60.00
1	REAR TAILLAMP (RHS)	SERVICEABLE	722.00	593.80
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER (RHS) (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR DOOR (RHS) (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-423.80	-359.76
			1,695.20	1,439.04
	SPECIAL NETT ITEMS			
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
			280.00	-
	<u>LABOUR</u>			
	TO REMOVE & REPLACE REAR REVERSE SENSOR.		100.00	40.00
	TO KNOCKING & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR TAILGATE, REAR END PANEL, REAR FENDER (RHS) AND REAR DOOR (RHS).		800.00	600.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	800.00
			1,900.00	1,440.00
	GRAND TOTAL		3,875.20	2,879.04



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SPF23002063/Rvy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,300-\$2,500

MKB

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

**Licensed Appraiser**