

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI23002068/RVP3M4**Date:** 21/06/2023REFERENCE

Insured/Claimant: WONG CHOK YIN Policy No: DMPCSNW00055842201

Date of Loss: 12/02/2023

Nature of Claim: OD

Claim No: SNM23D201151/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFA999S**

Make & Model: PORSCHE CAYENNE, 3.0 E3 TIP E6 (A)

Engine No: 194575

Reg. Date: 28/02/2020 (Man. Year: 2019)

Chassis No: WP1ZZZ9YZLDA03130

Colour: Black

Odometer: 75895 km

Engine Capacity: 2995 cc

Market Value/New Car Price: S\$392,000.00

Price:

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55R19

Rear Tyre Size: 255/55R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,500.10	22,034.20	8,465.90	27.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,950.00	4,440.00	6,510.00	59.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	41,450.10	26,474.20	14,975.90	36.13
- Excess (\$\$)	2,500.00	2,500.00	0.00	0.00
(\$\$)	38,950.10	23,974.20	14,975.90	38.45
+ GST 8.00/8.00% (\$\$)	3,116.01	1,917.94	1,198.07	38.45
Nett Amount (\$\$)	42,066.11	25,892.14	16,173.97	38.45

INSPECTION

Date of Assignment: 24/02/2023

Date Inspected: 24/02/2023 Inspected At:

Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2023)
Parts:	M1-SUV	PORSCHE CAYENNE 3.0 E3 TIP E6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFA999S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	2,531.20 F	*2,531.20 F
2	1		*TOWING COVER LH	Not Necessary	112.60 F	*- F
3	1		*TOWING COVER RH	Not Necessary	112.60 F	*- F
4	2		*EXPANDER NUT	Necessary	3.40 F	*3.40 F
5	4		*CLAMP	Necessary	20.00 F	*20.00 F
6	8		*RIVET	Necessary	15.20 F	*15.20 F
7	1		*GRILLE TRIM RH	Not Necessary	165.20 F	*- F
8	1		*FRONT BUMPER LOWER SPOILER	Scratched	1,072.60 F	*1,072.60 F
9	1		*GRILLE RH	Not Necessary	199.50 F	*- F
10	1		*BUMPER GUIDE RH	Not Necessary	100.80 F	*- F
11	8		*EXPANDER NUT	Necessary	13.60 F	*13.60 F
12	10		*BLIND RIVET	Necessary	18.00 F	*18.00 F
13	1		*BUMPER AIRDUCT RH	Not Necessary	79.30 F	*- F
14	1		*HEADLIGHT BRACKET RH	Not Necessary	80.60 F	*- F
15	1		*BUMPER RETAINER RH	Not Necessary	87.40 F	*- F
16	1		*FRONT SUBFRAME	Not Necessary	4,374.90 F	*- F
17	1		*REINFORCEMENT PLATE FOR SUBFRAME	Not Necessary	671.10 F	*- F
18	4		*COMBINATION SCREW	Necessary	38.00 F	*38.00 F
19	2		*COMBINATION SCREW	Necessary	29.40 F	*29.40 F
20	4		*SQUARE NUT	Necessary	23.20 F	*23.20 F
21	3		*HEXAGON SOCKET HEAD BOLT	Necessary	7.80 F	*7.80 F
22	3		*HEXAGON-HEAD BOLT	Not Necessary	9.30 F	*- F
23	1		*DOUBLE SCREW	Necessary	9.00 F	*9.00 F
24	4		*HEXAGON-HEAD BOLT	Necessary	88.40 F	*88.40 F
25	4		*HEXAGON-HEAD BOLT	Necessary	92.80 F	*92.80 F
26	1		*WISHBONE UPPER FRONT RH	Not Necessary	570.50 F	*- F
27	1		*WISHBONE UPPER REAR RH	Not Necessary	570.50 F	*- F
28	2		*HEXAGON-HEAD BOLT	Not Necessary	25.80 F	*- F
29	1		*GUIDE ROD RH	Bent	1,156.20 F	*1,156.20 F
30	1		*TRACK CONTROL ARM RH	Bent	762.60 F	*762.60 F
31	2		*12 POINT SOCKET	Necessary	35.60 F	*35.60 F
32	2		*HEXAGON NUT	Necessary	18.60 F	*18.60 F
33	2		*HEXAGON BOLT	Necessary	44.20 F	*44.20 F
34	2		*HEXAGON-HEAD BOLT	Necessary	23.40 F	*23.40 F
35	1		*SELF-LEVELLING SENSOR RH	Not Necessary	509.10 F	*- F
36	2		*HEXAGON NUT	Not Necessary	3.20 F	*- F
37	2		*HEXAGON-HEAD BOLT	Necessary	4.40 F	*4.40 F
38	1		*FRONT WHEEL CARRIER RH	Bent	1,700.20 F	*1,700.20 F
39	1		*ANGULAR-CONTACT BEARING FRONT RH	Necessary	529.60 F	*529.60 F
40	1		*WHEEL HUB FRONT RH	Bent	750.50 F	*750.50 F
41	4		*MULTIPLE-TOOTH SCREW	Necessary	34.80 F	*34.80 F
42	1		*POT	Bent	260.90 F	*260.90 F
43	2		*HEXAGON-HEAD BOLT	Necessary	16.20 F	*16.20 F
44	2		*HEXAGON-HEAD BOLT	Necessary	23.40 F	*23.40 F
45	2		*HEXAGON FLANGE SCREW	Necessary	28.40 F	*28.40 F
46	2		*HEXAGON NUT	Necessary	7.40 F	*7.40 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SPEED SENSOR	Not Necessary	325.00 F	*- F
48	2		*PN -014-740-11-/PAN-HEAD SCREW	Not Necessary	3.60 F	*- F
49	1		*ACCELERATION SENSOR	Not Necessary	162.50 F	*- F
50	2		*HEXAGON-HEAD BOLT	Necessary	6.60 F	*6.60 F
51	2		*HEXAGON-HEAD BOLT	Necessary	65.00 F	*65.00 F
52	1		*FRONT SHOCK ABSORBER RH	Not Working	1,584.00 F	*1,584.00 F
53	1		*FRONT SHOCK ABSORBER MOUNTING RH	Necessary	228.90 F	*228.90 F
54	1		*CAP	Necessary	28.00 F	*28.00 F
55	2		*(AJ06) NUT HEXAGON, WISHBONE	Bent	18.60 F	*18.60 F
56	1		*RUBBER STOP	Necessary	122.50 F	*122.50 F
57	1		*BOOT	Necessary	11.50 F	*11.50 F
58	1		*PROTECTION CAP	Necessary	26.60 F	*26.60 F
59	1		*CONCAVE SUPPORT	Necessary	46.70 F	*46.70 F
60	1		*CONCAVE WASHER	Necessary	60.00 F	*60.00 F
61	1		*SHOCK ABSORBER BRACKET RH	Necessary	786.40 F	*786.40 F
62	2		*COMBINATION SCREW	Necessary	24.00 F	*24.00 F
63	2		*HEXAGON NUT	Necessary	7.40 F	*7.40 F
64	4		*HEXAGON BOLT WITH WASHER	Necessary	34.80 F	*34.80 F
65	1		*SHOCK ABSORBER SPOILER RH	Not Necessary	102.00 F	*- F
66	1		*TIE-WRAP	Necessary	9.90 F	*9.90 F
67	2		*HEXAGON-HEAD BOLT	Necessary	19.80 F	*19.80 F
68	2		*HEXAGON NUT	Necessary	18.60 F	*18.60 F
69	2		*CLAMP	Not Necessary	143.80 F	*- F
70	4		*HEXAGON NUT	Not Necessary	13.20 F	*- F
71	1		*STABILIZER LINK RH	Bent	179.70 F	*179.70 F
72	1		*12 POINT SOCKET	Necessary	10.30 F	*10.30 F
73	1		*HEXAGON NUT SCREW, WISHBONE UPPER	Necessary	4.80 F	*4.80 F
74	1		*12 POINT SOCKET	Necessary	7.00 F	*7.00 F
75	1		*HEXAGON NUT SCREW, WISHBONE UPPER	Not Necessary	4.80 F	*- F
76	1		*STEERING GEAR	Bent	8,134.40 F	*8,134.40 F
77	1		*TRACK ROD RH	Bent	704.50 F	*704.50 F
78	2		*HEXAGON FLAT NUT	Not Necessary	8.60 F	*- F
79	2		*HEXAGON-HEAD BOLT	Necessary	23.40 F	*23.40 F
80	2		*HEXAGON HEAD BOLT (COMBI)	Necessary	48.20 F	*48.20 F
81	2		*SQUARE NUT	Necessary	11.60 F	*11.60 F
82	1		*MULTIPLE-TOOTH SCREW	Necessary	5.40 F	*5.40 F
83	1		*WHEEL COVER BLACK MAT	Deformed	349.90 F	*349.90 F
84	1		*COVER PLATE	Bent	76.70 F	*76.70 F
85	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **30,500.10** **22,034.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REPLACE FRT BUMPER & ALLL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,900.00	1,560.00
2	TO RESPRAY FRONT BUMPER, FRT RIM RH	New	1,800.00	1,300.00
3	TO REMOVE & REPLACE THE FRONT UNDER CARRIAGE RH INCLUDING SUBFRAME & STEERING GEAR	New	3,120.00	0.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	680.00	680.00
5	TO TRANSFER THE FRONT BUMPER SENSORS	New	300.00	150.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
8	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	New	300.00	0.00
Gross Labour Cost (S\$)			10,950.00	4,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >